

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**NM J-528**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>TEXAS PACIFIC OIL COMPANY</b>	8. Farm or Lease Name <b>Boyd</b>
3. Address of Operator <b>P. O. Box 1069 Hobbs, New Mexico</b>	9. Well No. <b>4</b>
4. Location of Well UNIT LETTER <b>B</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>23</b> TOWNSHIP <b>22-S</b> RANGE <b>37-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Penrose Skelly</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3333' DF</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Rig up. Pull Tbg. & B.P.
- Run Tbg. Spot Frac Sd. to 3670' in OH.
- Run Pkr. set @3600'. Squeeze off w/100 sks Incor plus 6-10 @ 1% Halad 9 plus 1% CA CL. Release Pkr. & Circ. Out.
- Run Frac. Tbg. & Pkr.
- Acidize w/500 gal. N.E. Acid across perfs.
- SOT w/15,000 gal. oil plus 15,000# 20/40 sd. plus 1/40 Adomite.
- Release Pkr. & Pull Tbg.
- Swab & Test.
- Place Well on Pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Stuart Sperry* TITLE Area Superintendent DATE 7-27-66

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: