

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name Langlie Mattix	
2. Name of Operator Anadarko Production Company		8. Farm or Lease Name Penrose Sand Unit	
3. Address of Operator P. O. Box 247 Hobbs, New Mexico 88240		9. Well No. 3	
4. Location of Well UNIT LETTER C , 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 22S RANGE 37E NMPM.		10. Field and Pool, or Wildcat Langlie Mattix	
15. Elevation (Show whether DF, RT, GR, etc.) 3341' GR		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Rig up well servicing unit. Pull tubing & Rods.
- Run 2-3/8" to T.D. at 3643'.
- Pump 500 sacks class "C" cement to plug back into 7" casing at 3426'. Pull tubing.
- Set a cast iron bridge plug at 3375'. Dump 5 sacks of cement on bridge plug.
- No 7" casing will be pulled. Set a 4" dry hole marker & abandon well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>M. J. [Signature]</i></u>	TITLE <u>Dist. Superintendent</u>	DATE <u>6-2-71</u>
APPROVED BY <u><i>[Signature]</i></u>	TITLE <u>SUPERVISOR DISTRICT 1</u>	DATE <u>JUN 4 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUN - 3 1971

OIL CONSERVATION COMM.
HOBBS, N. M.