

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)



1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name Langlie
2. Name of Operator ANADARKO PRODUCTION COMPANY		8. Farm or Lease Name Matrix Penrose Sand Unit
3. Address of Operator P. O. Box 247, Hobbs, New Mexico 88240		9. Well No. 5
4. Location of Well UNIT LETTER M 330 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 28 TOWNSHIP 22 S RANGE 37 E N.M.P.M.		10. Field and Pool, or Wildcat Langlie Matrix
15. Elevation (Show whether DF, RT, GR, etc.) Not available		11. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in well servicing unit. Pull tubing and rods.
2. Run 3400' of 4-1/2" 10.50 pipe with a packer to fracture treat.
3. Fracture treat using 60,000 gallons gelled brine with 1-1/2# SPG, staged with rock salt.
4. Pull frac tubing and rerun 2-3/8" tubing, rods and pump.
5. Place well back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE District Superintendent	DATE 1/14/70
APPROVED BY 	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		