

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTAFE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Langlie Mattix Penrose Sadr Unit
2. Name of Operator Anadarko Production Company	8. Farm or Lease Name Tract No. 26
3. Address of Operator Box 806, Eunice, New Mexico 88231	9. Well No. 1
4. Location of Well UNIT LETTER G 2310 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 28 TOWNSHIP 22S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Langlie Mattix
15. Elevation (Show whether DF, RT, GR, etc.) N. A.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Temporary Abandon <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RUPU and pull rods and tubing.
2. Run cast iron bridge plug on tubing and set @ 3310' in 7" 22# casing.
3. Dumped five sks cmt. through tubing on top of plug.
4. Pumped salt gel mud to surface.
5. Placed a swadge and vavle on top of csg. Closed valve.
- ~~6. Well plugged and abandoned.~~

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Runyan TITLE **Area Supervisor** DATE **10-16-74**

APPROVED BY John W. Runyan TITLE Area Supervisor DATE 10-16-74

CONDITIONS OF APPROVAL, IF ANY:

Excluded 10/17/74 (2nd)