NO. OF COPIES RECEIVED			France C. 100
DISTRIBUTION	DISTRIBUTION ANTA FE NEW MEXICO OIL CONSERVATION COMMISSION		Form C-103 Supersedes Old
SANTA FE			C-102 and C-103
FILE			Effective 1-1-65
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE	_		State x Fee
OPERATOR			5. State Oil & Gas Lease No.
			B-2330
SLINI	DRY NOTICES AND DEPOR	OTS ON WELLS	111111111111111111111111111111111111111
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
1.		, , , , , , , , , , , , , , , , , , ,	7. Unit Agreement Name
OIL GAS WELL WELL	OTHER-		Skelly Penrose "B" Uni
2. Name of Operator			8. Farm or Lease Name
Skelly Oil Company			Skelly Penrose "B" Unit
3. Address of Operator			9. Well No.
P. O. Box 1351, Midland, Texas 79701			A
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER E . 1980 FEET FROM THE North LINE AND 990 FEET			Langlie-Mattix
0411 221121	FEET FROM THE	FEET	FROM LATELLE PROPERTY.
THE West	32	22S RANGE 37E	
LINE, SEC	TION TOWNSHIP _	RANGE J/E	NMPM. ()
	15. Elevation (Shou	whether DF, RT, GR, etc.)	12. County
		3361' GR	T.e.s
16. Check	Appropriate Boy To Ind	icate Nature of Notice, Report of	
	INTENTION TO:		
NOTICE OF	INTENTION TO.	SUBSEQ	UENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANI	nou []	7 —
TEMPORARILY ABANDON	PEGG AND ABANI		ALTERING CASING
PULL OR ALTER CASING		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL ON ACTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQB	_
OTHER Add perforation	s and acidize	OTHER	
17. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pert	inent details, and give pertinent dates, inc	luding estimated date of starting any proposed
	lon, we propose addin		
	init and pull rods an		
2) Clean out to PBT	D of 3785'. Spot 25	0 gals. 7-1/2% acid.	
3) Run Gamma Ray No	utron Correlation Lo	g from 3785' to 2800'.	
4) Perforate 5-1/2'	OD casing with 2 sh	ots per foot at: 3701-37	05', 3708-3812', 3830-3832',
3837-3839' and 3			
	set RTTS packer at 36		
6) Acidize new perf	s. with 1000 gals. N	E acid. Swab test; pull	tubing and packer.
7) Run tubing and r	ods and return well	to producing status.	
10.11			
18. I hereby certify that the informati	on above is true and complete to t	he best of my knowledge and belief.	
	D. R. Crow	he best of my knowledge and belief.	DATE October 5, 1972
	D. R. Crow		DATEOctober 5, 1972
18. I hereby certify that the informati	D. R. Crow		

CONDITIONS OF APPROVAL, IF ANY: