

Form 1160-5
(July 1989)
(Formerly 7-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other Instructions on re-
verse side)

BLM Newell District

Modified Form No.

11060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

LC-030557 (A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Farney A-17

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Jalmat Tansill Y 7 R

11. SEC., T., R., M., OR BLK. AND
SUBST. OR AREA

S-17, T-23-S, R-36-E

12. COUNTY OR PARISH

Lea

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT..." for such proposals.)

1. ☐ OR,
WELL, ☒ GAS
WELL, ☐ OTHER

2. NAME OF OPERATOR
Lanexco, Inc.

3. Area Code & Phone No.
505-395-3056

4. ADDRESS OF OPERATOR
P.O. Box 1206 Jal, NM 88252

5. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

600 FWL & 1650' FWL

14. PERMIT NO.

15. EXPLANATION (Show whether op., st., or, etc.)

3475 DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOTING OR ACIDIZING

REPAIR WELL

(Other) Re-complete

PLUG OR ALTER CASING

MULTIPLE COMPLETION

ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(Note: Report results of multiple completion or Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMINENT OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

Move in and rig up pulling unit and reverse equipment,
Run drill collars, bit and tubing to 3556.
Drill out 5½" CIBP at 3556. Clean out to PBTD - 3650'.
Perfs at 3619-3640. Perforate additional perfs.
Acidize and swab test.
Fracture if necessary.
Place back on production.
Will notify BLM before work commences.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Supt.

DATE

11-8-90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

11-16-90

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side