

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLE
(Other instructions
reverse side)

CE
To

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A. H. Blinebry Fed. NCT-1

9. WELL NO.

12

10. FIELD AND POOL, OR WILDCAT

Blinebry & Drinkard

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA
Unit Letter H, Section 19,
T-22-S, R-38-E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

1. NAME OF OPERATOR

TEXACO Inc.

2. ADDRESS OF OPERATOR

P. O. Box 728, Hobbs, New Mexico 88240

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface Well is located 1980' from the North Line and 989'
from the East Line of Section 19, T-22-S, R-38-E, Unit Letter
'H', Lea County, New Mexico.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show above or below surface, etc.)

3334' (DF)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

1. STOP WATER SHUT-OFF

2. RILL OR ALTER CASING

3. WATER SHUT-OFF

4. REPAIRING WELL

5. FRACTURE TREAT

6. MULTIPLE COMPLETION

7. FRACTURE TREATMENT

8. ALTERING CASING

9. SHOOT OR ACIDIZE

10. ABANDON*

11. SHOOTING OR ACIDIZING

12. ABANDONMENT*

13. PAIR WELL*

X

14. CHANGE PLANS

(Other)

(Other) *Repair Communication

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

16. OTHER PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

TEXACO Inc. Proposes To Do The Following Work On Subject Well

1. Install BOP. Kill Blinebry & Drinkard Zones.
2. Pull Tubing from both zones.
3. Replace bad tubing.
4. Run Drinkard tubing w/Parallel String Anchor and Set in Model
'D' Packer.
5. Run Blinebry Tubing and latch into Parallel String Anchor.
6. Swab, take Packer Leakage Test & place on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Assistant District
Superintendent

DATE April 10, 1970

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
APR 13 1970
ARTHUR R. BROWN
DISTRICT SUPERINTENDENT

*See Instructions on Reverse Side