

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN \_\_\_\_\_ DATE \_\_\_\_\_  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NONE

7. UNIT AGREEMENT NAME

NONE

8. FARM OR LEASE NAME

A. H. Blinebry NCT-1

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Blinebry

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 29, 22-S, 38-E

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)  
At surface

Well located 1980' from the West Line, and 1980' from the North Line of Section 29, T-22-S, R-38-E, Lea County, N. M.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3382' (D. F.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☒  
☐  
☐  
☐

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

☐  
☐  
☐  
☐  
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

☐  
☐  
☐  
☐

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐  
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

We propose to do the following work on subject well:

1. Kill well with lease crude, pull pump equipment, set retrievable bridge plug at 5840', and dump 5' of sand on top of plug.
2. Perforate the Blinebry zone with two jet shots at 5624', 5629', 5634', 5638', 5654', 5720', 5755', 5759', 5766', 5774', 5794', and 5807'.
3. Acidize perforations with 1200 gals 15% NE acid in three equal stages with 250 pounds of moth balls between stages. Frac well with 20,000 gals gelled lease crude, and 20,000 pounds of sand. Swab well.
4. Swab well, recover load oil, Test, and place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED W. E. Morgan

(This space for Federal or State office use)

TITLE Assistant to the District

DATE July 18, 1966

Superintendent

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

JUL 18 1966

A. R. BROWN  
DISTRICT ENGINEER

\*See Instructions on Reverse Side