| BUREA       P. O.         BUREA       P. O.         BURDRY NOTICES       AND REPORTS ON WELLS         (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.         Use "APPLICATION FOR PERMIT-" for such proposals.)         OIL       CAS         WELL       OTHER         NAME OF OPERATOR         P.O. Box 728, Hobbs, New Mexico, 88240         LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*         Stee also space 17 below.)         At surface         2310' FNL & 330' FWL         15. ELEVATIONS (Show whether DF, ET, GE, etc.) | LC-C<br>0. IF INDIA:<br>7. UNIT AOBREMENT NAME<br>7. UNIT AOBREMENT NAME<br>8. FARM OR LEASE NAME<br>A. H. Blinebry Fed. NCT-1<br>9. WELL NO.<br>13<br>10. FIELD AND POOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. EBC., T., E., M., OR BLK. AND<br>BURNEY OR AREA |  |  |
|--|--|--|--|
| HODAL HOLD CS240         SUNDRY NOTICES AND REPORTS ON WELLS         (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.<br>Use "APPLICATION FOR PERMIT—" for such proposals.)         OIL       X       CAS         WELL       CAS       OTHER         NAME OF OPERATOR       Texaco Inc.         ADDRESS OF OPERATOR       P.O. Box 728, Hobbs, New Mexico, 88240         Location of well (Report location clearly and in accordance with any State requirements."         At surface         2310'       FNL & 330'         FWL   | 7. UNIT AGREEMENT NAME<br>8. FARM OR LEASE NAME<br>A.H. Blinebry Fed. NCT-1<br>9. WBLL NO.<br>13<br>10. FIELD AND POOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. ERC. T. B. M. OR BLK. AND  |  |  |
| (No not use this form for proposals to drill or to deepen or plug back to a different reservoir.<br>Use "APPLICATION FOR PERMIT-" for such proposals.)<br>OIL S WELL OTHER<br>NAME OF OPERATOR<br>Texaco Inc.<br>ADDRESS OF OPERATOR<br>P.O. Box 728, Hobbs, New Mexico, 88240<br>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2310' FNL & 330' FWL   | 7. UNIT AGREEMENT NAME<br>8. FARM OR LEASE NAME<br>A.H. Blinebry Fed. NCT-1<br>9. WBLL NO.<br>13<br>10. FIELD AND POOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. ERC. T. B. M. OR BLK. AND  |  |  |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.<br>Use "APPLICATION FOR PERMIT-" for such proposals.)<br>OIL WELL OTHER<br>NAME OF OPERATOR<br>Texaco Inc.<br>ADDRESS OF OPERATOR<br>P.O. Box 728, Hobbs, New Mexico, 88240<br>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2310' FNL & 330' FWL   | -<br>8. FARM OR LEASE NAME<br>A.H. Blinebry Fed. NCT-1<br>9. WBLL NO.<br>13<br>10. FIELD AND POOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. EBC., T. B., M., OR BLK. AND  |  |  |
| OIL X WELL OTHER<br>NAME OF OPERATOR<br>TEXACO Inc.<br>ADDRESS OF OPERATOR<br>P.O. BOX 728, Hobbs, New Mexico, 88240<br>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2310' FNL & 330' FWL   | -<br>8. FARM OR LEASE NAME<br>A.H. Blinebry Fed. NCT-1<br>9. WBLL NO.<br>13<br>10. FIELD AND POOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. EBC., T. B., M., OR BLK. AND  |  |  |
| WELL A WELL oTHER<br>NAME OF OPERATOR<br>Texaco Inc.<br>ADDRESS OF OPERATOR<br>P.O. BOX 728, Hobbs, New Mexico, 88240<br>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2310' FNL & 330' FWL  | -<br>8. FARM OR LEASE NAME<br>A.H. Blinebry Fed. NCT-1<br>9. WBLL NO.<br>13<br>10. FIELD AND POOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. EBC., T. B., M., OR BLK. AND  |  |  |
| NAME OF OPERATOR<br>Texaco Inc.<br>ADDRESS OF OPERATOR<br>P.O. Box 728, Hobbs, New Mexico, 88240<br>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2310' FNL & 330' FWL   | A.H. Blinebry Fed. NCT-1<br>9. WBLL NO.<br>13<br>10. FIELD AND FOOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. EBC. T. B. M. OR BLK. AND   |  |  |
| Texaco Inc.<br>ADDRESS OF OPERATOR<br>P.O. Box 728, Hobbs, New Mexico, 88240<br>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2310' FNL & 330' FWL   | A.H. Blinebry Fed. NCT-1<br>9. WBLL NO.<br>13<br>10. FIELD AND FOOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. EBC. T. B. M. OR BLK. AND   |  |  |
| ADDRESS OF OPERATOR<br>P.O. BOX 728, Hobbs, New Mexico, 88240<br>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2310' FNL & 330' FWL  | 9. WELL NO.<br>13<br>10. FIELD AND POOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. ERC. T. B. M. OR BLK. AND   |  |  |
| P.O. Box 728, Hobbs, New Mexico, 88240<br>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2310' FNL & 330' FWL   | 13<br>10. FIELD AND POOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. ERC. T. B. M. OR BLK. AND  |  |  |
| LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>2310' FNL & 330' FWL   | 10. FIELD AND FOOL, OR WILDCAT<br>Blinebry Oil & Gas<br>11. EBC., T., E., M., OR BLK. AND  |  |  |
| At surface<br>2310' FNL & 330' FWL   | Blinebry Oil & Gas   |  |  |
| 2310' FNL & 330' FWL   | 11. SEC., T., E., M., OR BLK. AND  |  |  |
|  | II. EBC., T., E., M., OR BLK. AND  |  |  |
|  |  |  |  |
| . PERMIT NO. 15. ELEVATIONS (Show whether DF, BT, GR, etc.)  | Sec. 29, T22S, R38E  |  |  |
| to. Subvations (Blow whether DF, ET, CK, etc.)   |  |  |  |
| 3375' G.L.   | 12. COUNTY OR PARISH 13. STATE   |  |  |
|  | Lea NM   |  |  |
| Check Appropriate Box To Indicate Nature of Notice, Report, or C   | )ther Data   |  |  |
| FOTICE OF INTENTION TO :   | ANT ENFORT OF:   |  |  |
| TEST WATER SHUT-OFF PELL OR ALTER CASING   |  |  |  |
|  | BEPAIRING WELL   |  |  |
|  | ALTERING CABING  |  |  |
|  | ABANDONMENT*   |  |  |
| (Other) (NOTE · Report remits  | of multiple completion on Well<br>etion Report and Log form.)  |  |  |
| <ol> <li>Perforated 7" casing with 2SPF: 5497,5505,11,30,37,44,49,59,42,51,58,62,67,76,83,91,5700,07,12,24,32,49,53,68,74,82,86,938,48,57,62,73,77,93,98,5912,31,35,39,51,55,59,69,75 and 598</li> <li>Acidize perforations with 12,000 gallons of 15% NEFE HCL in</li> <li>Frac with 124,000 gallons Cross-linked gel and 336,000# sand</li> <li>Run production equipment and place well on test.</li> <li>24 hour potential test Pm 87°/150<sup>W</sup>/1264<sup>GOR</sup>. Gravity 38.4.6</li> </ol>  | 97,5800,06,10,16,22,31,34,<br>32'.<br>4 equal stages.<br>1 in 4 equal stages.  |  |  |
|  |  |  |  |
|  | 60°F - Blinebry Oil and  |  |  |
| Gas zone.  | 60°F - Blinebry Oil and  |  |  |
| Gas zone.  | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD   | 60°F - Blinebry Oil and  |  |  |
| Gas zone.  | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD   | 60°F - Blinebry Oil and  |  |  |
| Gas zone.  | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD   | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD<br>HUY<br>MAY 20 1986   | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD   | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD<br>HUY<br>MAY 20 1986   | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD<br>HUY<br>MAY 20 1986<br>CARISBAD, NE MIMICO  | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD<br>HUN<br>MAY 20 1986   | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD<br>HULL<br>MAY 20 1986<br>CARISPAD, NE MIMICO   | 05 12 26   |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD<br>HUW<br>MAY 20 1986<br>CARISPAD, NE. MIMICO   | 60°F - Blinebry Oil and  |  |  |
| Gas zone.<br>ACCEPTED FOR RECORD<br>Huy<br>MAY 20 1986<br>CARISPAD, NE MIMICO<br>I hereby certify that the foregoing in true and correct<br>SIGNED HUMANING TITLE Dist. Adm. Supvr.  | 05 12 26   |  |  |

7. A Drenkind &

|  | DEPARTMEN   | ITED STATE  | :s "<br>INTERIØR: ~  | revers<br>To any gr   | tons on<br>e)                    | Form approved.<br>Budget Bureau No. 1004-0136<br>Expires August 31, 1985   |
|--|---|---|--|---|----------------------------------|--|
|  | BUREAU O  | F LAND MANA   | GEMENTO O  | N 10 10 10 10 10 10 10 10 10 10 10 10 10  |                                  |  |
| APPLICATIO   | ON FOR PERMIT   | TO DRILL,   | DEEPENOOR  | PLUG B  | ACK 88                           | LC-032104<br>26 CB INDIAN, ALLOTTER OR TRIBE NAME  |
|  |   | DEEPEN  | _  | UG BAC  |                                  | 7. UNIT AGREEMENT NAME   |
| S. NAME OF OPERATOR  | GAS OTESS   |   | SONB   | MULTIPL<br>Sons   | • 🗆                              | 8. PARM OR LEASE NAME  |
| Texaco Inc.  | •   |   |  |   |                                  | A.H. Blinebry Federal NC   |
|  |   |   |  |   |                                  | 13   |
| 4. LOCATION OF WELL (  | 28, Hobbs, Ne<br>Report location clearly an   | W Mexico  | 88240  |   |                                  | 10. FIELD AND POOL, OR WILDCAT   |
| 231(<br>At proposed prod. so   | 0' FNL & 330'   | FWL   | •  | eb (B.* )   | -                                | Blinebry Oil & Gas<br>11. AND SURVEY OF AREA   |
| 4. DISTANCE IN MILES   | AND DIRECTION FROM NEA  | BEET TOWN OR POST   | T OFFICE*  |   |                                  | Sec. 29, T-22-S, R-38-E  |
| / Miles Sou<br>10. DISTANCE FROM PROF  | theast of Eun   | ice, New M  | lexico   |   |                                  | _  |
| LOCATION TO NEARES   | BT  |   | 16. NO. OF ACRES IN  | LEASE   | 17. NO. OF                       | Lea New Mexic  |
| 18. DISTANCE PROM MOD  | g. unit line, if any)   | 330'  | 1855.12  |   | 10 141                           | 40   |
| OR APPLIED FOR, ON TH  | DRILLING, COMPLETED,<br>III LEASE, FT.  | 2333'   | 19. PROPOSED DEPTH   |   | 20. BOTARY                       | OR CABLE TOOLS   |
| 1. ELEVATIONS (Show wh   | ether DF, RT, GR, etc.)   | 2333 1  | 6280'  |   | Pu                               | <u>lling Unit</u>  |
| 3375' G.L.   |   |   |  |   |                                  | 22. APPROX. DATE WORK WILL START*  |
| J.   | I   | ROPOSED CASIN   | G AND CEMENTING  | PROGRAM   |                                  | February, 1986   |
| BILE OF ROLE   | SIZE OF CASING  | WEIGHT PER FO   |  |   |                                  |  |
| $\frac{17-1/2"}{12-1/4"}$  | 13-3/8"   | 48#   |  | ,   | 400 51                           | QUANTITY OF CEMENT   |
| 8-3/4"   | 9-5/8"  | 36#   | 2950   |   | 000 Sk                           | <u>s-Cement Circulated</u>   |
| 6-3/4"   | 4-1/2"  | 23#<br>11.6#  | 6828   |   | 000 Sk                           | S-Calc TOC @ 2857  |
| Wallta   | ently complet   | ed in the   | Drinkard   |   |                                  | s-Calc TOC @ 6621'   |
| D.H.C. of th   | 'has declined<br>e Blinebry an  |   |  | тиергу.   | . AIC                            | sed to temporarily<br>er production from<br>then be made for   |
| <pre>Line Blinebry D.H.C. of th completion p l) Pull rod l) Set CIBP l) Perforate 49, 59, 7 5700, 07, 31, 34, 3 69, 75 ar</pre>  | has declined<br>e Blinebry an<br>rocedure:<br>s, pump, inst<br>@ 6300' with<br>e following i<br>79, 89, 92, 5<br>, 12, 24, 32,<br>38, 48, 57, 6   | l sufficien<br>d Drinkard<br>20' cemen<br>ntervals w<br>602, 28, 3<br>49, 53, 6<br>2, 73, 77,   | ntly, appli<br>d. Followi<br>nd pull tub:<br>nt on top.<br>yith 2 SPF:<br>2, 38, 42,<br>8, 74, 82,<br>93, 98, 59   | cation<br>ng is t<br>5497,<br>51, 58<br>86, 97                                    | 5505<br>5505<br>62,<br>5800      | er production from<br>then be made for<br>ug-back and<br>, 11, 30, 37, 44,<br>67, 76, 83, 91,<br>0, 06, 10, 16, 22,<br>39, 51, 55, 59  |
| <pre>Line Blinebry D.H.C. of th completion p l) Pull rod; l) Set CIBP l) Perforate 49, 59, 5 5700, 07, 31, 34, 3 69, 75 ar CONTINUED ON</pre>  | has declined<br>e Blinebry an<br>rocedure:<br>s, pump, inst<br>@ 6300' with<br>e following i<br>79, 89, 92, 5<br>, 12, 24, 32,<br>38, 48, 57, 6<br>nd 5982'.<br>PAGE 2.                         | sufficien<br>d Drinkard<br>all BOP ar<br>20' cemen<br>ntervals w<br>602, 28, 3<br>49, 53, 6<br>2, 73, 77,<br>possal is to deepen<br>s give pertinent da | ntly, appli<br>1. Followi<br>ad pull tub<br>at on top.<br>with 2 SPF:<br>2, 38, 42,<br>8, 74, 82,<br>93, 98, 59<br>or plug back. give da<br>ta on subsurface loca                | cation<br>ng is t<br>ing.<br>5497,<br>51, 58<br>86, 97<br>12, 31<br>ta on present | 5505<br>, 62,<br>, 5800<br>, 35, | er production from<br>then be made for<br>ug-back and<br>, 11, 30, 37, 44,<br>67, 76, 83, 91,<br>0, 06, 10, 16, 22,<br>39, 51, 55, 59,<br>e mone and proposed new productive<br>true vertical depths. Give blowout |
| Life Blinebry<br>D.H.C. of th<br>completion p<br>l) Pull rod<br>2) Set CIBP<br>3) Perforate<br>49, 59,<br>5700, 07,<br>31, 34, 3<br>69, 75 ar<br>CONTINIED ON<br>ACCEPTOR PROCESSING A<br>e. If proposal is to dr<br>venter program, if any. | has declined<br>e Blinebry an<br>rocedure:<br>s, pump, inst<br>@ 6300' with<br>e following i<br>79, 89, 92, 5<br>, 12, 24, 32,<br>38, 48, 57, 6<br>nd 5982'.<br>BAGE From irectionally<br>b. L. | sufficien<br>d Drinkard<br>all BOP ar<br>20' cemen<br>ntervals w<br>602, 28, 3<br>49, 53, 6<br>2, 73, 77,<br>possal is to deepen<br>s give pertinent da | ntly, appli<br>1. Followi<br>ad pull tub<br>at on top.<br>with 2 SPF:<br>2, 38, 42,<br>8, 74, 82,<br>93, 98, 59<br>or plug back. give da<br>ta on subsurface loca                | cation<br>ng is t<br>ing.<br>5497,<br>51, 58<br>86, 97<br>12, 31<br>ta on present | 5505<br>, 62,<br>, 5800<br>, 35, | er production from<br>then be made for<br>ug-back and<br>67, 76, 83, 91,<br>0, 06, 10, 16, 22,<br>39, 51, 55, 59,  |
| <pre>the Blinebry D.H.C. of th completion p l) Pull rod l) Pull rod l) Set CIBP l) Perforate</pre>   | has declined<br>e Blinebry an<br>rocedure:<br>s, pump, inst<br>@ 6300' with<br>e following i<br>79, 89, 92, 5<br>, 12, 24, 32,<br>38, 48, 57, 6<br>nd 5982'.<br>BAGE From irectionally<br>b. L. | sufficien<br>d Drinkard<br>all BOP ar<br>20' cemen<br>ntervals w<br>602, 28, 3<br>49, 53, 6<br>2, 73, 77,<br>possal is to deepen<br>s give pertinent da | htly, appli<br>1. Followi<br>ad pull tub<br>at on top.<br>7 th 2 SPF:<br>2, 38, 42,<br>8, 74, 82,<br>93, 98, 59<br>or plug back, give da<br>ta on subsurface loca<br>Dist. Oper. | cation<br>ng is t<br>ing.<br>5497,<br>51, 58<br>86, 97<br>12, 31<br>ta on present | 5505<br>, 62,<br>, 5800<br>, 35, | er production from<br>then be made for<br>ug-back and<br>, 11, 30, 37, 44,<br>67, 76, 83, 91,<br>0, 06, 10, 16, 22,<br>39, 51, 55, 59,<br>e mone and proposed new productive<br>true vertical depths. Give blowout |
| <pre>the Blinebry D.H.C. of th completion p l) Pull rod l) Pull rod l) Set CIBP l) Perforate</pre>   | has declined<br>e Blinebry an<br>rocedure:<br>s, pump, inst<br>@ 6300' with<br>e following i<br>79, 89, 92, 5<br>, 12, 24, 32,<br>38, 48, 57, 6<br>nd 5982'.<br>BAGE From irectionally<br>b. L. | sufficien<br>d Drinkard<br>all BOP ar<br>20' cemen<br>ntervals w<br>602, 28, 3<br>49, 53, 6<br>2, 73, 77,<br>possal is to deepen<br>s give pertinent da | ntly, appli<br>1. Followi<br>ad pull tub<br>at on top.<br>with 2 SPF:<br>2, 38, 42,<br>8, 74, 82,<br>93, 98, 59<br>or plug back. give da<br>ta on subsurface loca                | cation<br>ng is t<br>ing.<br>5497,<br>51, 58<br>86, 97<br>12, 31<br>ta on present | 5505<br>, 62,<br>, 5800<br>, 35, | er production from<br>then be made for<br>ug-back and<br>, 11, 30, 37, 44,<br>67, 76, 83, 91,<br>0, 06, 10, 16, 22,<br>39, 51, 55, 59,<br>e mone and proposed new productive<br>true vertical depths. Give blowout |

## \*See Instructions On Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false. fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CONTINUED FROM PAGE 1

A. H. Blinebry Federal NCT-1 Well No. 13

Plug-Back and completion procedure continued:

- 4) Acidize perfs with 11,200 gallons of 15% NE-FE HCL in 4 stages.
- 5) Frac with 124,000 gallons cross-linked gel and 336,000 Lbs. sand in 4 stages.
- 6) Check for fill and c/o if necessary.
- 7) Run production equipment and place well on test.



.