


It should be noted that only a retrievable bridge plug (RBP) was set at 6000' on 7-16-91 with no cement on top. This RBP was set after we discovered that reperforation of the Blinebry Oil and Gas pool on \*4-11-91 accidentally shot perfs into and through String #2.

Currently, only the Blinebry Oil and Gas pool is producing to surface through Strings #1 and #2. Royalty and Working Interest are identical for all wells on this lease. Thus, production revenue is not impacted.

We respectfully request permission to continue our current mode of operation until such time that we re-enter (workover) String #2. We feel that casinghead gas that might migrate past the RTP would be of insignificant volume and pressure. Thus, pool damage to Blinebry Oil and Gas and Wantz Abo is unlikely to occur.

Please direct any questions to my attention at the above letterhead address or call me at (915) 688-7874.

Sincerely,



Don J. Bates

DJB:mym  
5\mmsst.ltr