NO. OF COPIES RECEIVED		· · · · · · · · · · · · · · · · · · ·	Form C-103
DISTRIBUTION	Ĵ		Supersedes Old
SANTA FE	NEW MEXICO OIL CON	SERVATION COMMISSION	C-102 and C-103
FILE		OERTATION COMMISSION	Effective 1-1-65
U.S.G.S.			
		÷	5a. Indicate Type of Lease
LAND OFFICE			State Fee X
OPERATOR			5. State Oil & Gas Lease No.
SUNDR	Y NOTICES AND DEPORTS ON	IWELLS	THE THE THE THE THE THE
SUNDRY NOTICES AND REPORTS ON WELLS (30 NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
1.	TORM CTOTY FOR SO	CH PHOPOSALS.)	
OIL X GAS WELL			7. Unit Agreement Name
2. Name of Cperator	OTHER-		
MORANCO			8. Farm or Lease Name
3. Address of Operator			Xmas
	1000 77-11		9. Well No.
	1860, Hobbs, New Me	X1CO	1
4. Location of Well			10. Field and Pool, or Wildagt
H 2	310 North	660	Driver July
ONI CEITER	FEET FROM THE	LINE AND FEET FROM	THE THE PARTY OF T
East	29 22	5 305	
THE LINE, SECTIO	TOWNSHIP	S 38E NMPM.	
mmmmmm			
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	3381 KB	33/1 GL	Lea ()
Check A	ppropriate Boy To Indicate N	Portuga of Maria Diagram	
NOTICE OF IN	TENTION TO	Nature of Notice, Report or Oth	
NOTICE OF IN	TENTION TO:	SUBSEQUENT	REPORT OF:
	(FT)		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
ОТНЕЯ			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1603.			
			, similar in proposition
Move in unit to Plug and Abandon well.			
1. Set bridge plug on wire line a coost			
1. Set bridge plug on wire line @ 6800'± cap with 35' (3 sacks) cement.			
2. Pull what casing is available.			
(calculated top of cement is 3930')			
	•		
After pulli:	ng casing, go in ho	le with tubing, displ	
*	5 3, 30 III 1101	re wren caping, arspr	ace noie with mud.
4. Set 50 sack	plug across casing	atub	
	pray across casting	stub.	
5 Set 75 sagk	nl	05.44	
J. Dec 75 Sack	plug from 2400' to	2700'.	
C 0 - 1 - 1 - 0 - 0		₩ 1.00	
6. Set 100 sac	c plug from 1200' to	1500'. THE COMMISSION M	HIST BE NOTICED OF
6. Set 100 sack plug from 1200' to 1500'. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF			
7. Set surface	plug and dry hole m		INE BEGINNING OF
,		TO BE APPROVED.	THE C-103
		· · · · · · · · · · · · · · · · · · ·	
18. I hereby certify that the information a	bove is true and complete to the best of	f my knowledge and helief	
		,g. www ocasols	
(loe > ()		Agent	March 21 10mm
SIGNED .	TITLE	3	March 31, 1976
Joe T. Janzca			AND PADE
	ry Serton		apri 3 13/6
PPROVED BY	st I, Sepv.		

CONDITIONS OF APPROVAL, IF ANY:

CIL CONSTRUCTION CONSTRUCTION