May 28, 1969

New Maxico Oil Conservation Commission P. O. Box 871 Santa Fe, New Maxico 87501

Attention: Mr. A. L. Porter

Re: Amendment, Order No. MC-1658 A. H. Blinebry (NCT-1) Well No. 28 Les County, New Mexico

Gentlemen:

Attached is Form C-107, Application F r Multiple Completion, as required under the provisions of Rule 112-A, requesting permission to dually complete TEXACO Inc. A. H. Blinebry (HCT-1) Well No. 28 located in Unit A of Section 29, Township 22 South, Range 38 East, Les County, New Mexico. Order No. 1658 dated September 6, 1965, granted TEXACO Inc. permission to dually complete the subject well and produce oil from the Tubb Gas Pool and the Drinkard Pool.

TEXACO Inc. respectfully requests the smendment of Order Ho. 1658 to permit a dual completion in the Blinebry and Drinkard Pools. The Tubb Pool is no longer economically productive in this well and has been abandoned.

Yours very truly.

J. G. Blevins, Jr. Assistant District Superintendent

BRE-cg Attachments

MOCC -Hobbs

NEW 1 1CO OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO APPLICATION FOR MULTIPLE COMPLETION

Form C-107

5-1-61

May 29	11 32	AN JEA	
		HM 168	
Country		111 13	D 1

			County	
Operator	TEXACO Inc.		County Lea	Date May 28, 1969
Address	Box 728, Hobbs,	New Mexico 88240	Lease A.H. Blinebry (NCT-1)	Well No. 28
Location of Well	Unit A	Section 29	Township 22 South	Range 38 East
zones	he New Mexico Oil Conse within one mile of the su wer is yes, identify one s	bject well? YES A	NO; Operator Lease, an	a well in these same pools or in the same

TEXACO Inc., A.H. Blinebry (NCT-1), Well No. 26.

. The following facts are submitted:	Upper Zone	Intermediate Zone	Lower Zone
a. Name of Pool and Formation	Blinebry		Drinkard
b. Top and Bottom of			
Pay Section	5742* - 6041*		70021 - 72571
(Perforations)			1002 - 1231
c. Type of production (Oil or Gas)	011		011
d. Method of Production			
(Flowing or Artificial Lift)	Artificial lift		Artificial lift

	(1 loube encer 1 bo of 10)
□ ≭ □ b.	 Diagrammatic Sketch of the Multiple Completion, showing all casing strings, including diameters and setting depths, central- izers and/or turbolizers and location thereof, quantities used and top of cement, perforated intervals, tubing strings, including diameters and setting depth, location and type of packers and side door chokes, and such other information as may be pertinent. Plat showing the location of all wells on applicant's lease, all offset wells on offset leases, and the names and addresses of operators of all leases offsetting applicant's lease. Waivers consenting to such multiple completion from each offset operator, or in lieu thereof, evidence that said offset opera- tors have been furnished copies of the application.* Electrical log of the well or other acceptable log with tops and bottoms of producing zones and intervals of perforation in-
	dicated thereon. (If such log is not available at the time application is filed it shall be submitted as provided by Rule 112-A.)
	L Corporation, Box 1938, Roswell, New Mexico Man, Box 1718, Hobbs, New Mexico 88240
Solar Oj	11 Company, Box 5596, Hidland, Texas 79701
E. A. He	Anson, Box 1515, Roswell, New Mexico
Vestern	Oil Fields, Box 1147, Hobbs, New Mexico 88240
Americas	Petrofina Company of Texas, Box 1311, Big Spring, Texas
6. Were all opera	ttors listed in Item 5 above notified and furnished a copy of this application? YES X NO

date of such notification ney 20, 1909 IJ ventarel

CERTIFICATE: I, the undersigned, state that I am the Aset. Dist. Superintendent the

(company), and that I am authorized by said company to make this report; and that this report was prepared under my supervision and direction and that the facts stated therein are true, correct and complete to the best of my knowledge.

Signature

TEXACO Inc.

Should waivers from all offset operators not accompany an application for administrative approval, the New Mexico Oil Conservation Commis-sion will hold the application for a period of twenty (20) days from date of receipt by the Commission's Santa Fe office. If, after said twenty-day period, no protest nor request for hearing is received by the Santa Fe office, the application will then be processed.

NOTE: If the proposed multiple completion will result in an unorthodox well location and/or a non-standard proration unit in one or more of the producing zones, then separate application for approval of the same should be filed simultaneously with this application.

May 28, 1969

Guif Oli Corporation, P.O. Box 1938, Noswell, New Maxico 88201 R.M. Moran, P.O. Box 1718, Hobbs, New Maxico 88240 Solar Oli Company, P.O. Box 5596, Midland, Texas 79701 E.A. Hanson, P.O. Box 1515, Roswell, New Mexico 88201 Western Oli Fields, P.O. Box 1147, Hobbs, New Mexico 88240 American Petrofina Company of Texas, P.O. Box 1311, Big Spring, Texas 79720

Gentlemen:

Attached is an application by TEXACO inc. to dually complete the A.H. Blinebry (NCT-1) Well No. 28 in the Blinebry and Drinkard Pools. The well is located in Unit A of Section 29, Township 22 South, Range 38 East, Lea County, New Mexico. Also attached are three copies of a valver consenting to such multiple completion and self-addressed, stamped envelopes for your convenience.

If you have no objections to this application, please approve and forward one of the attached valvers to the New Mexico OII Conservation Commission in Santa Fe and return one to TEXACO inc. Your prompt handling of this matter will be appreciated.

Yours very truly.

J.G. Blevins, J.M. Assistant District Superintendent

BRH-bh

Attachments

NMOCC

New Mexico OII Conservation Commission P.O. Box 871 Santa Fe, New Mexico 87501

Gentlemen:

This is to advise that TEXACO inc. has notified us of the intention to dually complete their A.H. Blinebry (NCT-I) Well No. 28 (Blinebry and Drinkard Pools) located in Unit A of Section 29, Township 22 South, Range 38 East, Lea County, New Mexico.

The undersigned hereby waives the right of protest and hearing and has no objection to TEXACD inc. dually completing this well.

> By_____ Company_____

Dete



BLINEBRY FIELD AREA E. LEA COUNTY, NEW MEXICO SCALE DRAWN BY FMR DATE



March & Brield Add Barth - Charles and Add Barth

Sketch - Dual Tubingless Completion

Name: A.H. BLINEBRY (NCT-1) WELL NO. 28 Field: BLINEBRY AND DRINKARD Date: MAY 27, 1969

	DEDAD.	TMI T OF THE IN		TRIPLICATE*		Bureau No. 42-R14
		GEOLOGICAL SURV			LC=03210	
	SUNDRY NO	DTICES AND REPO	<u>محمد المحمد ا</u>		6. IF INDIAN, ALL	DETER OR TRUE NAS
(Do not us	se this form for pro Use "APPL	posals to drill or to teepin o ICATION FOR PERATT-U	NIJ WELLJ Beluginack (Ga different re	eservoir.	None	
1.		MALET 10			None 7. univ Agreemen	T RAME
WELL LA V	VELL OTHER				None	ust A. M. M. M.
2. NAME OF OPERA	TEXACO I	nce			8. FARM OR LEASE	bry Fed. NC
3. ADDRESS OF OP	ERATOR	· · · · · · · · · · · · · · · · · · ·			9. WELL NO.	ory Fed. No
4. LOCATION OF W		n clearly and in accordance w			28	1000 - 1000 - 1000 1000 - 1000 -
See also space At surface	17 below.)	a clearly and in accordance w	ith any State requirements.	·	10. FILLD AND FOO Blinebry	
North Lir		from the East Li on 29, T-22-S, R-3		A Tee	11. ALC, P. K. M. SUBVEY OF Sec. 29, T	OR BLE AND
14. PERMIT NO.	NEW HEALCOS	15. ELEVATIONS (Show wh	ether DF, RT, GR, etc.)		12. COUNTY OB PA	BYOTAL TO ANTA
Regular			376' (D. F.)		Lea	New Mexi
16.	Check A	Appropriate Box To Indi	cate Nature of Notice	Report or Oth		
	NOTICE OF INT				T REPORT OF:	
TEST WATER S	HUT-OFF	PULL OR ALTER CASING	WATER SHUT-			NG WELL
FRACTURE TREA	AT	MULTIPLE COMPLETE	FRACTURE TRI			G CASENO
SHOOT OR ACID Repair well		ABANDON*	SHOOTING OR		ARANDO	
(Other)	L]	CHANGE PLANS	(NOTE :	Report results of	n the Blin multiple complet	ton on Wall
17. DESCRIBE PROPO proposed woi	SED OR COMPLETED O	PERATIONS (Clearly state all period tionally drilled, give subsurfa			on Report and Log cluding estimated	
nent to this w	vork.) *		and meabured u		depths for all man	ters and somes per
1. Pull	led producti	on rods and tubin	D ON SUBJECT WELL		가 가 있었다. 가 같은 가 있다. 같은 것 같은 것 같은 것 같은 것	이 일 가죽 것 오 정 것 이번 법하 수 지, 역 역
2. Ran 3. Perf 1 JS 5800 5880	RBP and set forated 2 7/ SPF @ 5721'.	'8" O. D. Casing i from 5742' to 57 916', 5821', 5826' 902', 5914', 5961'	g. n Tubb string (B] h51, 57h81 to 575	Linebry Zon	5801-12	And
2. Ran 3. Perf 1 JS 5800 5880 5999	RBP and set forated 2 7/ SPF @ 5721, 5',5812', 58 5',5895', 59 9', and 6019 tted acid ov	<pre>@ 6200'. '8" 0. D. Casing i from 5742' to 57 16', 5821', 5826' 02', 5914', 5961'</pre>	g. n Tubb string (B] 45', 5748' to 575 , 5845', 5850', 5 , 5964', 5983' t ns 5721' to 6019'	Linebry Zon 51', 5795 [€] , 5857',5870' to 5988', 5 '. Acidize	5801. 58761, 9901, at N/3000	And a constant of the second s
2. Ran 3. Perf 1 JS 5800 5880 5999 4. Spot gals 5. Frac sand 7000	RBP and set forated 2 7/ SPF @ 5721', 5',5812', 58 5',5895', 59 7', and 6019 tted acid ov 5. 15% NE Ac c down 2 7/8 i and 1/40#	<pre>@ 6200'. '8" 0. D. Casing i from 5742' to 57 916', 5821', 5826' 902', 5914', 5961' '0 er new perforatio eid in 1h stages W " 0. D. Casing W/ Adomite per gal. g 8 ball sealers</pre>	g. n Tubb string (B] 45', 5748' to 579 , 5845', 5850', 9 , 5964', 5983' t ns 5721' to 6019' /2 Ball sealers t 30,000 gal. gelle in 4 stages of 80	Linebry Zon 51', 5795 [®] , 5857',5870' to 5988', 5 '. Acidize between sta ed brine W/ 500, 8000,	5801. 58761, 59901, d N/3000 ges. /1# 20-40 7000, and	
2. Ran 3. Perf 1 JS 5800 5880 5999 4. Spot gals 5. Frac sand 7000 seal	RBP and set forated 2 7/ SPF @ 5721', 5',5812', 58 5',5895', 59 9', and 6019 tted acid ov s. 15% NE Ac c down 2 7/8 d and 1/40# J gals. Usin lers after 3:	<pre>@ 6200'. '8" 0. D. Casing i from 5742' to 57 916', 5821', 5826' 902', 5914', 5961' '0 er new perforatio eid in 1h stages W " 0. D. Casing W/ Adomite per gal. g 8 ball sealers</pre>	g. n Tubb string (B] 45', 5748' to 579 , 5845', 5850', 9 , 5964', 5983' t ns 5721' to 6019' /2 Ball sealers t 30,000 gal. gelle in 4 stages of 80 after 1st and 2nd	Linebry Zon 51', 5795 [®] , 5857',5870' to 5988', 5 '. Acidize between sta ed brine W/ 500, 8000,	5801. 58761, 59901, d N/3000 ges. /1# 20-40 7000, and	And a second sec
 2. Ran 3. Perf 1 JS 5800 5880 5999 4. Spot gals 5. Fraction sand 7000 seal 6. Swat 	RBP and set forated 2 7/ SPF @ 5721', 5',5812', 58 5',5895', 59 9', and 6019 tted acid ov s. 15% NE Ac c down 2 7/8 d and 1/40# J gals. Usin lers after 3: 5, Test, pla	@ 6200'. '8" O. D. Casing i from 5742' to 57 16', 5821', 5826' 02', 5914', 5961' 'o rer new perforatio id in 1h stages W '' O. D. Casing W/ Adomite per gal. g 8 ball sealers rd stage. ce Blinebry Zone	g. n Tubb string (B] 45', 5748' to 579 , 5845', 5850', 9 , 5964', 5983' t ns 5721' to 6019' /2 Ball sealers t 30,000 gal. gelle in 4 stages of 80 after 1st and 2nd	Linebry Zon 51', 5795 [®] , 5857',5870' to 5988', 5 '. Acidize between sta ed brine W/ 500, 8000,	5801. 58761, 59901, d N/3000 ges. /1# 20-40 7000, and	Apple and a set of the set of
2. Ran 3. Perf 1 JS 5800 5880 5999 4. Spot gals 5. Frac sand 7000 seal	RBP and set forated 2 7/ SPF @ 5721', 5',5812', 58 5',5895', 59 9', and 6019 tted acid ov s. 15% NE Ac c down 2 7/8 d and 1/40# J gals. Usin lers after 3: 5, Test, pla	 @ 6200'. '8" O. D. Casing i from 5742' to 57 '57.5742' to 57 '57.5742' to 57 '02', 5914', 5961' '04 to 57 '04 to 57	g. n Tubb string (B] 45', 5748' to 579 , 5845', 5850', 9 , 5964', 5983' t ns 5721' to 6019' /2 Ball sealers t 30,000 gal. gelle in 4 stages of 80 after 1st and 2nd	Linebry Zon 51', 5795 5 5857',5870' to 5988', 5 '. Acidize between sta ed brine W/ DOO, 8000, I stage, an	5801. 58761, 59901, d N/3000 ges. /1# 20-40 7000, and	An and a final second and a second a second and a second a se
2. Ran 3. Perf 1 JS 5806 5886 5999 4. Spot gals 5. Frac sand 7000 seal 6. Swat	RBP and set forated 2 7/ SPF @ 5721', 5',5812', 58 5',5895', 59 9', and 6019 tted acid ov s. 15% NE Ac c down 2 7/8 d and 1/40# J gals. Usin lers after 3: 5, Test, pla	 @ 6200'. '8" O. D. Casing i from 5742' to 57 '16', 5821', 5826' '02', 5914', 5961' '04', 5961' '06', 5821', 5826' '06', 5821', 5821', 5826' '06', 5821', 5821', 5826' '06', 5821', 5821', 5826' '06', 5821', 5826' '06', 5821', 5821', 5826' '06', 5821', 5826' '06', 5821', 5826', 5826' '06', 5821', 5826', 5	g. n Tubb string (B) 45', 5748' to 579 , 5845', 5850', 9 , 5964', 5983' t ns 5721' to 6019' /2 Ball sealers t 30,000 gal. gelle in 4 stages of 80 after 1st and 2nd on production. Assistant Distri	Linebry Zon 51', 5795 5 5857',5870' to 5988', 5 '. Acidize between sta ed brine W/ DOO, 8000, I stage, an	5801 58761, 9901, d N/3000 ges. /1# 20-40 7000, and d 10 ball	An and a final second and a second a second and a second a se
 2. Ran 3. Perf 1 JS 5806 5886 5999 4. Spot gals 5. Frac sand 7000 seal 6. Swat 18. I hereby certify SIGNED (This space for APPROVED BY	RBP and set forated 2 7/ SPF @ 5721', 5',5812', 58 5',5895', 59 9', and 6019 tted acid ov s. 15% NE Ac c down 2 7/8 d and 1/40# d gals. Usin lers after 3: b, Test, pla that the foregoing	@ 6200'. '8" O. D. Casing i from 5712' to 57 16', 5821', 5826' '02', 5911, 5961' 'o rer new perforatio id in 1h stages W '' O. D. Casing W/ Adomite per gal. g 8 ball sealers rd stage. ce Blinebry Zone is true and correct TITLE ffice use)	g. n Tubb string (B] 45', 5748' to 579 , 5845', 5850', 9 , 5964', 5983' t ns 5721' to 6019' /2 Ball sealers t 30,000 gal. gelle in 4 stages of 80 after 1st and 2nd on production. Assistant Distri	Linebry Zon 51', 5795 5 5857',5870' to 5988', 5 '. Acidize between sta ed brine W/ DOO, 8000, I stage, an	5801. 58761, 59901, 29901, 2000, 2000, and 2000, and 200	An and a final second and a second a second and a second a se
 2. Ran 3. Perf 1 JS 5806 5886 5999 4. Spot gals 5. Frac sand 7000 seal 6. Swat 18. I hereby certify SIGNED (This space for APPROVED BY	RBP and set forated 2 7/ SPF @ 5721', 5',5812', 58 5',5895', 59 9', and 6019 tted acid ov s. 15% NE Ac c down 2 7/8 d and 1/40# D gals. Usin lers after 3: b, Test, pla that the toregoing	@ 6200'. '8" O. D. Casing i from 5712' to 57 16', 5821', 5826' '02', 5911, 5961' 'o rer new perforatio id in 1h stages W '' O. D. Casing W/ Adomite per gal. g 8 ball sealers rd stage. ce Blinebry Zone is true and correct TITLE ffice use)	g. n Tubb string (BJ 45', 5748' to 579 , 5845', 5850', 9 , 5964', 5983' t ns 5721' to 6019' /2 Ball sealers t 30,000 gal. gelled in 4 stages of 80 after 1st and 2nd on production. Assistant Distri Superintendent	Linebry Zon 51', 5795°, 5857',5870' to 5988', 5 '. Acidize between sta ed brine W/ 000, 8000, I stage, an i.ct	5801 58761, 59901, 59901, d N/3000 ges. /1# 20-h0 7000, and d 10 ball DATE MEY DATE MEY	An and a final second and a second a second and a second a se
 2. Ran 3. Perf 1 JS 5806 5886 5999 4. Spot gals 5. Frac sand 7000 seal 6. Swat 18. I hereby certify SIGNED (This space for APPROVED BY	RBP and set forated 2 7/ SPF @ 5721', 5',5812', 58 5',5895', 59 9', and 6019 tted acid ov s. 15% NE Ac c down 2 7/8 d and 1/40# D gals. Usin lers after 3: b, Test, pla that the toregoing	<pre>@ 6200'. '8" O. D. Casing i from 5742' to 57 02', 5821', 5826' 02', 5914', 5961' '. rer new perforatio eid in 1h stages W " O. D. Casing W/ Adomite per gal. g 8 ball sealers rd stage. ce Blinebry Zone ha true and correct TITLE Mcc use) ANY: TITLE</pre>	g. n Tubb string (B] 45', 5748' to 579 , 5845', 5850', 9 , 5964', 5983' t ns 5721' to 6019' /2 Ball sealers t 30,000 gal. gelled in h stages of 80 after 1st and 2nd on production. Assistant Distri Superintendent M ctions on Reverse Side	Linebry Zon 51', 5795°, 5857',5870' to 5988', 5 '. Acidize between sta ed brine W/ 000, 8000, I stage, an	5801, 58761, 9901, d N/3000 ges. /1# 20-40 7000, and d 10 ball DATE DATE	An and a final second and a second a second and a second a se