DISTRIBUTION		Form C-103
	· ·	Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and G-103 Effective 1-1-65
FILE)	7
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee.
OPERATOR		5. State Oil & Gas Lease No.
		B-3480-1
SLINI	DRY NOTICES AND DEPORTS ON WELLS	
(DO NOT USE THIS FORM FOR	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
•	TOTAL TOTAL TERMINE - (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL WELL	OTHER+	
. Name of Operator		8. Farm or Lease Name
Gulf Oil Corporation		P P C-la (NOP A)
. Address of Operator		R. E. Cole (NCT-A) 9. Well No.
Bex 670, Hobbs, New M	lext on 882k0	
. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER N	1075 FEET FROM THE SOUTH LINE AND 2395 FEET FE	
UNII LEITER,	FEET FROM THE CINE AND FEET FR	
THE West Line, sec	CTION 16 TOWNSHIP 22-8 RANGE 37-1 NM	
THE THE LINE, SEC	CTION TOWNSHIP RANGE NM	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	338h gt.	Tee
Chec	k Appropriate Box To Indicate Nature of Notice, Report or	
		Other Data ENT REPORT OF:
NOTICE OF	THE ENTION TO.	INT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
PERFORM REMEDIAL WORK	REMEDIAL WORK	ALTERING CASING
	L COLUMNIES DRIVE AND A DEVICE	
=	CHANGE BLANS CASING TEST AND CENTURE	PLUG AND ABANDONMENT
=	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB OTHER	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER Plug back and P	CHANGE PLANS CASING TEST AND CEMENT JOB OTHER	
7335' ID, 7313' PB. Plans have be	casing test and cement Job other	ing estimated date of starting any proposed P set at 7200 Can RP
other Plug back and r 17. Describe Proposed or Completed work) SEE RULE 1703. 7335' TD, 7313' PB. Plans have buith 2 sacks of cemen	casing test and cement JQB OTHER complete in the Abo Operations (Clearly state all pertinent details, and give pertinent dates, included the state abandon the Silurian sense with CI Bit. Test casing and BP with 1000%. Perforate 70 and 6885-87 with 4 JHPF. Treat new perforations	P set at 7200'. Cap BP
other Plug back and resorring Plug back and resorring Proposed or Completed work) see Rule'1 fo3. 7335' ID, 7313' PB. Plans have be with 2 sacks of cemen 6805'-07', 6846-48' at 28% NE acid. Flush with the sacks of the plush with the plush w	casing test and cement Job complete in the Abo Operations (Clearly state all pertinent details, and give pertinent dates, included the state of th	P set at 7200'. Cap BP
other Plug back and r. 7. Describe Proposed or Completed work) SEE RULE 1703. 7335' ID, 7313' PB. Plans have be with 2 sacks of cemen 6805'-07', 6816-48' at 28% NE acid. Flush with 28% NE acid. Fl	CASING TEST AND CEMENT JOB OTHER OT	P set at 7200'. Cap BP casing at 6770-72', with 4000 gallons of
other Plug back and r. 7. Describe Proposed or Completed work) SEE RULE 1703. 7335' ID, 7313' PB. Plans have be with 2 sacks of cemen 6805'-07', 6816-48' at 28% NE acid. Flush with 28% NE acid. Fl	casing test and cement Job complete in the Abo Operations (Clearly state all pertinent details, and give pertinent dates, included the state of th	P set at 7200'. Cap BP casing at 6770-72', with 4000 gallons of