

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-934	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name -
2. Name of Operator Exxon Corporation	8. Farm or Lease Name New Mexico "S" State
3. Address of Operator Box 1600, Midland, TX 79701	9. Well No. 26
4. Location of Well UNIT LETTER L, 2310' FEET FROM THE South LINE AND 400 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 22-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Eunice San Andres South
15. Elevation (Show whether DF, RT, GR, etc.) 3379' D.F.	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull plastic-lined tubing with Brown Husky M-1 Packer. Run C.I.B.P. on workstring and set @ approximately 3825'. Cap bridge plug with 20' cement. Circulate hole with 9.5#/gal mud laden brine. Pull workstring. Establish free point of 4½" csg. If casing free below 1040', cut and pull 4½" csg. Spot a 100' cmt. plug through tubing from 940'-1040' with 35 sxs. If casing free above 1040' shoot csg. @ 1040'. Squeeze 35 sxs. cmt. down 4½" csg. in cut @ 1040'. Follow cmt. with rubber plug. Leave top of plug @ 940'. Cut and pull 4½" csg. Spot cmt. plugs through tubing as follows:

- 100' plug below the Ogallala and across the surface csg. shoe from 261'-361' with 35 sxs.
- 10' plug at the surface.

Rig well head for abandonment and install marker.

100' plug @ 4½" stab
" " " top soil

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

SECTION HEAD

DATE

12-11-74

APPROVED BY

Chris. Signed by

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: