

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-10.
Revised 10

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ For ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. Name of Operator
American Exploration Company

2. Address of Operator
2100 RepublicBank Center, Houston, Texas 77002

3. Location of Well

UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM
THE West LINE, SECTION 30 TOWNSHIP 22S RANGE 38E NEARBY.

15. Elevation (Show whether DF, RT, GR, etc.)

3329'

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This lease was acquired from Kirby Exploration Company by American Exploration Company effective May 1, 1988.

We propose to test the ABO Pool by perforating 7012-16', 6904-10', 6895-6900', 6829-34', 6750-55', 6738-42', 6688-92', 6679-83', 6667-71', 6638-43'. RIH w/RBP & pkr. Set plug @ 7100 & pkr. @ 6940'. Swab test perfs. Acidize perfs 7012-26 w/1000 gals. 15% NEFE + additives. Swab test perfs. If unsuccessful, retrieve plug & set @ 6950' w/pkr. at 6770' Acidize perfs 6829-6910' w/4200 gals. 15% NEFE + additives. If unsuccessful, set plug @ 6800' & pkr. @ 6550'. Swab test perfs. Acidize perfs 6639-6755 w/10,000 gals. 15% NEFE + additives. Swab test perfs. If unsuccessful, retrieve BP & set @ 7100 w/pkr. @ 6550'. Swab test perfs. If unsuccessful, set plug @ 6550' & pkr. @ 6200'. Swab test Drinkard perfs 6318-6436'. Acidize w/4000 gals. 15% NEFE + additives. Swab test perfs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Marty McClanahan

TITLE Production Dept.

DATE 8/25/88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE SEP 2'88