

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Cossatot "H"	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Drinkard	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator	
John H. Hendrix	
3. Address of Operator	
403 Wall Towers West, Midland, Texas 79701	
4. Location of Well	
UNIT LETTER L 2310 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 13 TOWNSHIP 22-S RANGE 37-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
3340' DF	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up Well Service pulling unit.
2. Run tubing and set retrievable bridge plug @ 7000'.
3. Spot 450 gallons of 15% LSTNE acid. Pull tubing.
4. Perforate @ 6616', 6652', 6673', 6710', 6728', 6747', 6765', 6783', 6804', 6828', 6848', 6859', 6870', 6892', 6919', 6936', 6955', 6966', and 6981' w/1 3/8" jet per interval.
5. Acidize with 8450 gallons 15% LSTNE acid.
6. Swab to test well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paula Pendleton TITLE Accountant DATE 6-11-73

APPROVED BY _____ TITLE _____ DATE _____