

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
5. State Oil & Gas Lease No. _____	
7. Unit Agreement Name _____	
8. Farm or Lease Name Lowe	
9. Well No. 1	
10. Field and Pool, or Wildcat Langlie - Mattix SR-Qn.	
12. County Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- \_\_\_\_\_

2. Name of Operator  
Petro-Search, Inc.

3. Address of Operator  
1010 Lamar Bldg. - Suite 1800 Houston, TX 77002

4. Location of Well  
UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM  
THE East LINE, SECTION 26 TOWNSHIP 22S RANGE 37E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3315' RKB

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POOH w/ rods, pump & tubing.
2. Set CIBP at  $\pm$  3450'. Dump bail cement to 3415' (35').
3. Perforate at 450'. Pump 75 sxs cement w/ 2% Calcium Chloride down casing to fill casing annulus.
4. Cut off wellhead. Set 10 sx plug at surface.
5. Erect abandonment marker.

APPROVED BY JERRY SEXTON  
DISTRICT SUPERVISOR  
10-11-84

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

WED Debbie Reynolds TITLE Regulatory Analyst DATE 12-11-84

APPROVED BY JERRY SEXTON DISTRICT SUPERVISOR TITLE \_\_\_\_\_ DATE DEC 18 1984

CONDITIONS OF APPROVAL, IF ANY: