Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I	IL CONSERVATION	N DIVISION			
P.O. Box 1980, Hobbs NM 88241-1980	2040 Pacheco	 	WELL API NO.		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM	87505	30-025-25131 5. Indicate Type of Lease		
			STATE	FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
1. Type of Well:			Walter Lynch		
WELL X WELL	OTHER				
2. Name of Operator			8. Well No.		
Marathon Oil Company	· · · · · · · · · · · · · · · · · · ·		6		
3. Address of Operator P.O. Box 2409. Hobbs. NM 88240			9. Pool name or Wildcat Blinebry 011 & Gas (011)		
4. Well Location Unit Letter F: 2310 Feet From The North Line and 1980 Feet From The West Line					
Unit Letter F: 2310 Feet From The NOTTH Line and 1980 Feet From The West Line					
Section 1	Township 22-S Ra	nge 37-E	ммрм Lea	County	
	10. Elevation (Show wheth	er DF, RKB, RT, GR, etc. 3353)		
11. Check Appro	opriate Box to Indicate		Papart or Other Det		
NOTICE OF INT	1	SEQUENT REPOR			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	AL TERMS	<u></u>	
		l Hichie	L_ ALTERING		
TEMPORARILY ABANDON L	CHANGE PLANS L_	COMMENCE DRILLING	OPNS. L.J. PLUG AND	ABANDONMENT L	
PULL OR ALTER CASING	6 ·	CASING TEST AND CE	MENT JOB		
OTHER: Reacidize Blinebry Perfor	ations X	OTHER:			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed					
work) SEE RULE 1103.			on, meaning committee that of a	micing any proposed	
		to the second second			
MIRU pulling unit. POOH w/rods & pump. ND wellhead. NU BOPE. POOH w/production tbg. RIH w/RBP & set at 100°. Pressure test. RIH w/pkr & set at 80°. Pressure test. Rel pkr and RBP. POOH.					
PU pkr. RU testers. RIH w/workstring, testing tbg. Set pkr at 5715'.					
Acidize Blinebry perfs 5724-5806' w/3500 gals 15% Ferchek acid w/100 1.3 SC ball sealers. Flush w/water. Rel pkr & POOH, reset pkr at 5590'. Swab back acid load. Rel pkr at 5590'. POOH, lay down.					
RIH w/production string. SN at 8812'. TAC at 5590'.					
ND BOP. NU wellhead. RIH w/pump and rods. RD pulling unit. Turn well to production.					
I hereby certify that the information above is true an	d complete to the best of my knowledge	and belief.			
SIGNATURE BILLY COOK	TITL	E Records Processo	Dr DATE	8/19/97	
TYPE OR PRINT NAME Kelly Cook		1	TELEPHONE NO	393-7106	
(This space for State Use)					
ORIGINAL SIGNED BY CHRIS DISTRICT I SUPERVIS	OR /				
APPROVED BY		int die	DATE	4 1 97	
CONDITIONS OF ADDROVAL IF ANY.		· 1 			

