

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

~~NEW MEXICO~~ **Oil Cons. Division**
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Pronghorn Management Corporation

3. Address and Telephone No.

P.O. Box 1772 Hobbs, N.M. 88241 505-393-9176

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL - 1980' FEL

S19 - T23S - R33E

5. Lease Designation and Serial No.

NMLC 068848

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Marshall Federal #6

9. API Well No.

30-025-25151

10. Field and Pool, or Exploratory Area

Cruz Delaware

11. County or Parish, State

Lea

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in p & a equipment
2. P.O.H w/ production equipment
3. Set C.I.B.P. @ $\pm 4950'$
Cap w/ 35' cement.
4. Circulate hole w/ mud laden fluid
5. Stretch, cut, & pull casing. $\pm 3000'$
6. Spot cement plug 50' in and out of stub. Tag plug. @ 3000'
7. Spot cement plug 100' @ 8 5/8" shoe @ 1245'.
1145' - 1295' - Tag plug (Will work for next plug) Set @ 1300'
8. Set surface plug. Cut off wellhead. Clean location. Erect derrick

RECEIVED
1998 NOV 30 P 2:43
BUREAU OF LAND MGMT.
HOBBS, NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed

Title

Date

(This space for Federal or State office use)

Approved by **(ORIG. SGD.) DAVID R. GLASS**
Conditions of approval, if any:

Title

PETROLEUM ENGINEER

Date

DEC 10 1998