WELL API NO.   SAME	Office		f New Mex				Davis	Form	25 100
30-032-3355	District I	Energy, winterars	wiw I talula	ii 1000u1003	WRII AI	PI NO	VC A12	ou Maich	LJ, 17
SIL South First, Areas, NM 57210  DEFENDATE, THE PROBLEM STATE STA		OIL CONTRE	17 A MTA 17	DIMICION	THE IN		25356		
STATE FEED    Santa Fe, NM 87500    Santa Fe, NM 97500    Santa Fe, NM 87500    Santa Fe	811 South First, Artesia, NM 87210				5. Indicat				
Sunday   S	District III								
200 South Packers, Santa Re, NM 87505  COLOR USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A PROPOSALS TO DRILL ON THE PROPOSALS TO		Santa	re, NM 875	ouo					
CO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PULG SACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well: OI We	2040 South Pacheco, Santa Fe, NM 8750				o. State C	ni & Gas I	Lease INC	) <b>.</b>	
8. Well No. Chewrood U.B.A. Tac.  S. Address of Operator  19. Pool name or Wildcat  20. Exercise No. 1.50  10. Elevation (Show whether DR. RRB, RT, GR, etc.)  11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUS AND ABANDON ALTERING CASING  TEMPORARILY ABANDON OHANGE PLANS COMPLETION CHANGE PLANS  PULL OR ALTERING CASING  COMMENCE DRILLING OPNS. PLUG AND ABANDON ABANDONMENT  CASING TEST AND CHARMY ABANDON ABANDON ABANDON ABANDONMENT  CASING TEST AND CHARMY ABANDON ABANDON ABANDON ABANDONMENT  CASING TEST AND CHARMY ABANDON ABANDON ABANDONMENT  CASING TEST AND CHARMY ABANDON ABANDON ABANDON ABANDONMENT  CASING TEST AND CHARMY ABANDON ABANDON ABANDONMENT  CASING TEST AND CHARMY ABANDON ABANDON ABANDON ABANDON ABANDONMENT  CASING TEST AND CHARMY ABANDON ABAN	(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVOIR. USE "APPROPOSALS.)  1. Type of Well:	OPOSALS TO DRILL OR TO PLICATION FOR PERMIT* (	DEEPEN OF	R PLUG BACK TO A			_	ement N	ame:
17   18   18   18   18   19   19   19   19		_ Other		<u></u>	9 Well N	Jo			-
3. Address of Operator P.O. Bex 1159 Middard, TX 79702  4. Well Location Unit Letter P: 330 feet from the SOUTH line and 757 feet from the EXCET line Section 16 Township 225 Range 378 NMPM County 122 County 12	•					10.			
## P.O. Bex 1150 Hidland, TX 79702  4. Well Location  Unit Letter P: 330 feet from the SOUTH line and 757 feet from the Section 16 Township 228 Range 378 NMPM County 122						ame or Wi	ldcat		
Unit Letter P 330 feet from the SOUTH line and 757 feet from the Section 16 Township 228 Range 378 NMPM County LEA 10. Elevation (Show whether DR, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING COMMENCE DRILLING OPNS. ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:  OTHER: OTHER: OTHER CASING NULTIPLE COMPLETION CEMENT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  POR W/FROD EQUY. DIRIPED 4 SX SD; TROGED @ 5420'. SWAREED. FRACD 3774'-3998' W/20,202 GALS FORM & 95,080# SAND. RIE W/TEG, FURP & RODG; TEG @ 3982'. RETURNED  WERL TO PRODUCTION.  WORK PERFORED 3/22/00 - 4/3/00  TITLE RESTLATORY O.A. DATE 7/25/00  THE DATE DATE		70702			1				
Unit Letter F : 330 feet from the SOUTH line and 757 feet from the 22ST line and 757 feet from		13104		···- <del></del>	1 200 20/5		<u> </u>	<del></del>	
Section 16 Township 228 Range 378 NMPM County 129A  10. Elevation (Show whether DR, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CEMENT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  RCH W/PROD EXPT. INSPEC 4 SX SD; TRACED @ 5420'. SWAESED. FRACD 3774'-3998' W/20, 202 CRUS FROM & 95,080# SAND. RUH W/THS, FUMP & RODS; TEG @ 3982'. RETURNED  WEELL TO PRODUCTION.  MCRK PERFCRASED 3/22/00 - 4/3/00  TITLE RESULATIONY O.A. DATE 7/25/00 TOTHER TITLE RESULATIONY O.A. DATE 7/25/00 Telephone No. (9151687-714  This space for State use)		330 feet from t	he <b>SOUT</b>	H line and	757	_ feet from	the	EAST	lin
10. Elevation (Show whether DR, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLUG AND ABANDONMENT COMMENCE DRILLING OPNS.  PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  PCH W/PROD EQPT. DUMPED 4 SX SD; TMGED @ 5420'. SWARSHED. FRACD 3774'-3998' W/20, 202 GALE FORM & 95,080% SAND. RIN W/TBG, FUMP & RODG; TEG @ 3982'. REFURNED  WELL TO PRODUCTION.  MCRK PERFORMED 3/22/00 - 4/3/00  hereby certify that the information above is true and complete to the best of my knowledge and belief.  TITLE REGULATORY O.A. DATE 7/25/09  Telephone No. (915) 687-714  This space for State use)				ange 37F	NMPM		County	, <del>T</del>	IFB.
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    PERFORM REMEDIAL WORK   PLUG AND ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   COMPLETION   CASING TEST AND CEMENT JOB    OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  PCH W/PROD EQPT. DUMPED 4 SX SD; TAGGED & 5420'. SWARBED. FRACD 3774'-3998'  W/20, 202 GRUE FORM & 95,080# SAND. RIH W/TRG, FUMP & RODS; TBG & 3982'. RETURNED  WELL TO PRODUCTION.  WORK PERFORMED 3/22/00 - 4/3/00  THE PROPERTY O.A. DATE 7/26/00  THE RESULATORY O.A. DATE 7/26/00  THE RESULATORY O.A. DATE 7/26/00  TELEPHONE NO. (915) 687-714  This space for State use)	Section 16						County		-carl
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING PEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT PULL OR ALTER CASING   MULTIPLE   COMPLETION   CEMENT JOB   DTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  POR W/PROD EQFT. DIMPED 4 SK SD, TAGGED @ 5420'. SWARDED. FRACD 3774'-3998' W/20,202 GALS FORM & 95,080# SAND. RIH W/TBG, FUMP & RODS; TBG @ 3982'. RETURNED WELL TO PRODUCTION.  WORK PERFORMED 3/22/00 - 4/3/00  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE ALPHAY  TITLE REGILATORY O.A. DATE 7/25/00  TEMPOVED BY  TITLE DATE  DATE  ALTERING CASING  COMMENT CASING  CASING TEMPORY.  ALTERING CASING  CASING TEMPORY.  ALTERIOR CASING  CASING TEMPORY.  ALTERING CASING  CASING TEMPORY.  ALTERIOR CASING  CASING TEMPORY.  ALTERING CASING  CASING TEMPORY.  ALTERIOR CASING  CASING TEMPORY.		10. Elevation (5/10	with the state of	a, and, at, oa, c	,				
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING PEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT PULL OR ALTER CASING   MULTIPLE   COMPLETION   CEMENT JOB   DTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  POR W/PROD EQFT. DIMPED 4 SK SD, TAGGED @ 5420'. SWARDED. FRACD 3774'-3998' W/20,202 GALS FORM & 95,080# SAND. RIH W/TBG, FUMP & RODS; TBG @ 3982'. RETURNED WELL TO PRODUCTION.  WORK PERFORMED 3/22/00 - 4/3/00  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE ALPHAY  TITLE REGILATORY O.A. DATE 7/25/00  TEMPOVED BY  TITLE DATE  DATE  ALTERING CASING  COMMENT CASING  CASING TEMPORY.  ALTERING CASING  CASING TEMPORY.  ALTERIOR CASING  CASING TEMPORY.  ALTERING CASING  CASING TEMPORY.  ALTERIOR CASING  CASING TEMPORY.  ALTERING CASING  CASING TEMPORY.  ALTERIOR CASING  CASING TEMPORY.	11 Chec	k Appropriate Box to	Indicate.	Nature of Notice	Report o	or Other	Data		
PERFORM REMEDIAL WORK PLUG AND ABANDON ABANDONMENT ABANDON			, maioato 1					)E·	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING COMPLETION CASING TEST AND CEMENT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  POH W/PROD EQPT. DURIPED 4 EX SD, TAGGED © 5420'. SWAREED. FRACD 3774'-3998' W/20, 202 GRAS FORM & 95,080# SAND. RIH W/TEG, FUMP & RODS; TEG © 3982'. RETURNED WELL TO PRODUCTION.  WORK PERFORMED 3/22/00 - 4/3/00  THE COMPLET TO PRODUCTION.  DATE 7/25/00  THE PROSULTION OF			,,, <u>,,,</u> ,						SINIC
ABANDONMENT CASING TEST AND CEMENT JOB  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  POH W/PROD EQPT. DEMPED 4 SK SD; TAGGED @ 5420'. SWAEEED. FRACD 3774'-3998' W/20,202 GALS FOAM & 95,080# SAND. RIH W/TEG, FUMP & RODS; TEG @ 3982'. RETURNED WELL TO PRODUCTION.  WORK PERFORMED 3/22/00 - 4/3/00  THE W/TEG WINDOWS OF THE W/TEG WINDOWS OF THE WINDOWS OF T	ZEHFOHM REMEDIAL WORK (	PLUG AND ABANL		DEMIEDIAL WORK		LXI	ALIEP	III OAS	טווע
CASING TEST AND CEMENT JOB  OTHER:  OT	TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	LING OPNS	. $\square$			JT
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  POH W/FROD EQFT. DUMPED 4 SK SD; TAGGED @ 5420'. SWARESED. FRACD 3774'-3998' W/20,202 GALS FORM & 95,080# SAND. RIH W/TEG, FUMP & RODS; TEG @ 3982'. RETURNED WELL TO PRODUCTION.  WORK PERFORMED 3/22/00 - 4/3/00  hereby certify that the information above is true and complete to the best of my knowledge and belief.  GIGNATURE TITLE REQULATORY O.A. DATE 7/25/00  Telephone No. (915)687-714  This space for State use)  APPROVED BY									<b>V</b> I
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  POH W/FROD EQFT. DUMPED 4 SK SD; TAGGED @ 5420'. SWAEBEED. FRACD 3774'-3998' W/20,202 GALS FORM & 95,080# SAND. RIH W/TEG, FUMP & RODS; TEG @ 3982'. RENURNED WELL TO PRODUCTION.  WORK PERFORMED 3/22/00 - 4/3/00  hereby certify that the information above is true and complete to the best of my knowledge and belief.  GIGNATURE TITLE REQULATORY O.A. DATE 7/25/00  Telephone No. (915)687-714  This space for State use)  APPROVED BY	PULL OR ALTER CASING				)		ADAIN	JOHNIE	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  PCH W/PROD EQPT. DUMPED 4 SX SD, TAGGED 6 5420'. SWAREED. FRACD 3774'-3998' W/20,202 GALS FORM & 95,080# SAND. RIH W/TBG, FUMP & RODS; TBG 6 3982'. RETURNED WELL TO PRODUCTION.  WORK PERFORMED 3/22/00 - 4/3/00  hereby certify that the information above is true and complete to the best of my knowledge and belief.  GIGNATURE J. R. RIPLEY  TITLE RESCULATORY O.A. DATE  Telephone No. (915)687-714  This space for State use)  APPROVED BY  TITLE DATE	OLE ON ALTEN ONO.			CEMENT JOB	)		ADAM	JOHNE	
W/20,202 GALS FORM & 95,080# SAND. RIH W/TBG, FOMP & RODS; TBG @ 3982'. RETURNED WELL TO PRODUCTION.  WORK PERFORMED 3/22/00 - 4/3/00  hereby certify that the information above is true and complete to the best of my knowledge and belief.  GIGNATURE J. K. RUPLEY  TITLE REGULATORY O.A. DATE 7/25/00  Telephone No. (915)687-714  This space for State use)  APPROVED BY  TITLE DATE	OTHER:	COMPLETION		CEMENT JOB OTHER:					
TITLE REGULATORY O.A. DATE 7/26/00  Type or print name J. K. RIPLEY  Telephone No. (915) 687-714  This space for State use)  APPROVED BY  TITLE  DATE	OTHER:  12. Describe Proposed or Comp of starting any proposed wor or recompilation.	COMPLETION  Cleted Operations (Clearly Ck). SEE RULE 1103. For	y state all per	CEMENT JOB  OTHER:  rtinent details, and completions: Attac	give pertine h wellbore o	liagram of	cluding	estimated	l date
APPROVED BY DATE DATE	OTHER:  12. Describe Proposed or Composed work of starting any proposed work or recompilation.  POH W/PROD EQPT. DUMP W/20,202 GALS FOAM & 9 WELL TO PRODUCTION.	COMPLETION  cleted Operations (Clearly k). SEE RULE 1103. For the second	y state all per or Multiple C	OTHER: rtinent details, and Completions: Attac	give pertine h wellbore o	liagram of	cluding	estimated	l date
	OTHER:  12. Describe Proposed or Compostarting any proposed work or recompilation.  PCH W/PROD EQPT. DUMP: W/20,202 GALS FOAM & 9 WELL TO PRODUCTION.  WORK PERFORMED 3/22/00  hereby certify that the information all signature of the composition of the compositi	completion  eleted Operations (Clearly  k). SEE RULE 1103. For  ED 4 SX SD; TAGGED 6-  5,080# SAND. RIH W/  - 4/3/00	y state all per or Multiple Co. 5420'. St. TBG, FUMP	OTHER: rtinent details, and Completions: Attack WABBED. FRACD 3 & RODS; TEG @ 39	give pertiner h wellbore of	liagram of  URNED	OATE	estimated comple	date etion
	OTHER:  12. Describe Proposed or Compos of starting any proposed work or recompilation.  PCH W/PROD EQPT. DUMP: W/20,202 GALS FOAM & 9 WELL TO PRODUCTION.  WORK PERFORMED 3/22/00  hereby certify that the information all GIGNATURE J. K. RIPLE Type or print name J. K. RIPLE This space for State use)	completions (Clearly k). SEE RULE 1103. For the second sec	y state all per or Multiple Co. 5420'. State all	OTHER: rtinent details, and Completions: Attack WABBED. FRACD 3 & RODS; TBG @ 35	give pertiner h wellbore of	JENSO	DATE	estimated comple	d date etion