

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-25518
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2274
7. Lease Name or Unit Agreement Name RL
8. Well No. 1
9. Pool name or Wildcat CRUZ - BONE SPRING
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator TOCO L. L. C.
3. Address of Operator P. O. BOX 888, HOBBS, NEW MEXICO 88241	4. Well Location Unit Letter <u>L</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>16</u> Township <u>23S</u> Range <u>33E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-6-97 per Gaye
Set 100' cmt plug from 9413' to 9313' covering perf, tag.
Left 6 jts 2 7/8" tbh cmtd in 7 5/8" csg. Top fish 9005'. SN @ bottom of fish-9189'.
Set 100' cmt plug from 8050' to 7950' covering D. V. Tool.
Set 100' cmt plug from 5150' to 5050', 50' in & 50' out of 10 3/4" shoe, tag.
Set 100' cmt plug from 2100'.
Set 100' cmt plug from 1352' to 1252' 50' in & 50' out T. O. S.
Set 100' cmt plug from perf below 13 5/8" shoe @ 748', 50' in 50' out, tag.
Set 10 sx surf plug.
Cut off csg. head, weld on Dry Hole Marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gaye Heard TITLE MANAGER DATE 08/06/97

TYPE OR PRINT NAME GAYE HEARD TELEPHONE NO. (505) 393-2727

(This space for State Use)

APPROVED BY Larry W. Hill TITLE MANAGER DATE APR 08 1998

CONDITIONS OF APPROVAL, IF ANY:

TCI rev

per