Office Office	State of New M	fexico	_
District I E	E TV Minerals and Notice I December		Form C-103
District II		Revised March 25, 1999 WELL API NO.	
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-25519
1000 Rio Brazos Rd., Aztec NM 87410 2040 South Pacheco		5. Indicate Type of Lease	
District IV Santa Fe NIM 97505		STATE 🔀 FEE	
2040 South Pacheco, Santa Fe, NM 87505			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			7 Lease Name or Unit A
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A PROPOSALS.)			7. Lease Name or Unit Agreement Name:
PROPOSALS.)  1. Type of Well:			Drinkard "B" NCT
Oil Well Gas Well Other			1122
2. Name of Operator			
Chevron USA, Inc.		8. Well No.	
3. Address of Operator			9. Pool name or Wildcat
4. Well Location 15 Smith Rd. Midland, Tx 79705			
			Brunson, Drinkard, ABO-South
Unit Letter 0: 880 feet from the south line and 1980 feet from the			
30	ownship 22-S Ra	ange 38-E	NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
PERFORM REMEDIAL WORK PLUG AND ABANDON FOR PRINCIPLE OF STATE OF S			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE REPORTED			ALTERING CASING
PULL OR ALTER CASING AND THE			ARANDONIMENT
COMPLETIO	on U	CASING TEST AND CEMENT JOB	
OTHER:			
12. Describe proposed or completed operations		OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date or recompilation.  SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
1. Notify OCD 24hrs and			
1. Notify OCD 24hrs prior to MI & RU 2. Set 5 1/2 CIBP + 6675 great 25 to 25			
2. Set 5 1/2 CIBP +-6675, spot 25sx plug 6675-6475 (Drinkard-ABO) WOC Tag  3. Displace hole w/MLF, 9.5 # Brine w/25# Ge1 p/BBL.			
	~ L = 1	/BBL.	
3. Spot 238X plug 3600_3000(0100m)			
6. Spot 25sx plug 2600-2400(B-salt) WOC Tag. 7. Spot 25sx plug 1300 1100(8.576)			
7. Spot 25sx plug 1300-1100(8 5/8 shoe, T-salt)WOC Tag. 8. Perf 4 holes @ 300, sqz 75sx plug 300-surf 5 1/2 X 8 5/8 (surf) WOC Tag. 9. Install dry hole marker.			
9. Install dry hole marker.	rug 300-surf 5	1/2 X 8 5/8 (s	urf) WOC Tag.
		•	TWITTEN TO BE NOTIFIED 24
		1.3	NULL DISH BROWNING OF NO DECRADONS FOR THE C-103 HERONED.
		되었다. TXT	140 OPERATIONS FOR THE C-103 General
I book a series of the series			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE / . K. Menhor		HES Special	
Type or print name (3, R, B)eds oe		,	
(This space for State use)			Telephone No. 915, 687, 7153
·		· · · · · ·	
APPPROVED BY Conditions of approval, if any:	CAR W WINK	:D 67	DATE
	OC FIELD REPRES	SENTATIVE II/STAFF	