

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☐ For ☒

5. State Oil & Gas Lease No.
936209 A & B

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name Walter Lynch
3. Address of Operator P.O. Box 1861, Midland, TX 79702	9. Well No. 5
4. Location of Well UNIT LETTER M 330 FEET FROM THE South LINE AND 330 FEET FROM West LINE, SECTION 1 TOWNSHIP 22S RANGE 37E N.M.P.M.	10. Field and Pool, or Wildcat Waltz Granite Wash Pool
15. Elevation (Show whether DF, RT, GR, etc.) 3350.3 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER Recomplete & dual ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU, Uset Mud "R" pkr 7303' & trip out & laydown 2 7/8 prod strg & pkr. RIH w/Otis Permalach Pkr, Ostsd w/type "N" Landing nipple X-over sub 2 7/8 WS. Set pkr 7300' Set plug in "N" profile on WL, unlatch from divider, circ out oil into tanks & load hole w/5% KCL wtr. RIH w/RBP & set 7000'. GOI perf Tubb Gas Zone w/DML Densi-Jet XIX, 4" CG, 19 GC, .48 EH 6006-18, 6032-40, 6049-57, 6079-91, 6096-6102. 6106-12, 6118-22, 6132,40, All 1JSP2F total 40 holes. RIH w/Baker FB Pkr, on 2 7/8 tbg. press test BP to 6000#. Spot 4 bbl 15% Nefehcl from 6150/5982. PUH to 5850' & set pkr. West & Newsco acdz Tubb perfs 6000/6150 w/6000 gal 50 quality foam 15% Nefehcl in 5 equal stages. Commence load recovery thru variable choke size. Swab if necessary. West & Newsco frac Tubb perfs 6000/6150 w/66,000 gal 70 quality 5% KCL foam & 75,000# 20-40 SD in 2 equal stages. Swab if necessary. Test well. Kill well, equalize, unset & POH w/FB pkr, LD pkr, RIH w/ret. head & retrieve RBP. RIH w/Ostsd, X-Over sub Otis sliding door on 2 7/8 Pro. strg. Latch on seal divider 7300' equalize & open sliding door let well clean up. Run Otis F-stop & set in profile of sliding door. Swab, dry & kick off. Retrieve F-stop & close sliding door. Equalize & retrieve plug. Produce Tubb gas thru csg. & Granite Wash oil thru tbg run pkr leakage test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dee Ann Kemp

TITLE Accounting Assistant I

DATE 7-24-81

DATE Signed by
Larry Sexton
DATE 7-24-81

APPROVED BY Dee Ann Kemp

TITLE Accounting Assistant I

DATE 7-24-81

CONDITIONS OF APPROVAL, IF ANY: