

**N.M. Oil Cons. Division**

**P.O. Box 1980**

**Hobbs, NM 88241**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

*Pronghorn Management Corporation*

3. Address and Telephone No.

*P.O. Box 1772 Hobbs N.M. 88241 505-393-9176*

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

*2600' FSL - 1230' FWL*

*S19-T23S-R33E*

5. Lease Designation and Serial No.

*NMLC068848*

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

*Marshall Federal #8*

9. API Well No.

*30-025-08361*

10. Field and Pool, or Exploratory Area

*Cave Delaware*

11. County or Parish, State

*Lea*

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Move in production equipment, pull w/ production equipment

2. Set C.I.B.P. @  $\pm 4950'$

Cap w/ 35' cement.

3. Circulate hole w/ mud laden fluid.

4. Spot 100' plug @ 2900' - 3000'

5. Spot 100' plug @ 1173' - 1213' - 8 5/8" shoe. (Wait work for Seal Plug.)

6. Set surface plug. Cut off well head.

Erect day hole marker. Clear location.

RECEIVED  
1998 NOV 30 P 2:43  
BUREAU OF LAND MGMT.  
HOBBS, NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed

*Pratt New*  
Title

Date *11/30/98*

(This space for Federal or State office use)

Approved by

*Robert A. Glass*  
Title *PETROLEUM ENGINEER*

Date *DEC 10 1998*

Conditions of approval, if any.

RECEIVED  
DEC 04 38  
CLM  
HOWELL, NM