

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
LG-286

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Amoco Production Company 3. Address of Operator P. O. Box 68, Hobbs, NM 88240 4. Location of Well UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 13 TOWNSHIP 23-S RANGE 34-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3359 GL	7. Unit Agreement Name 8. Farm or Lease Name State GA 9. Well No. 1 10. Field and Pool, or Wildcat Wildcat Strawn 12. County Lea
--	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to PXA well per the following:

Spot a 50 sack cement plug from 11930' to 11430'. Run freepoint in 9-5/8" casing. Cut casing one joint above free point and pull. Run in hole with tubing and spot a 150' plug from 5160'-5010' from top of Delaware across 12-3/8" casing shoe. Spot a 150' plug 50' in and 50' out of 9-5/8" casing stub with 55 sacks of cement. Spot 200' plug from 1698'-1898' across top of Rustler with 150 sacks of cement. Spot 100' plug from 687'-787' with 75 sacks of cement 50' above and 50' below the 20" casing shoe. Spot 15 sack surface plug and erect PXA marker.

0+4-NMOCD-H 1-Hou 1-W. Stafford-Hou 1-DMF 1-Susp

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Freeman TITLE Asst. Admin. Analyst DATE 2/25/82
ORIGINAL SIGNED BY
JERRY SEXTON
APPROVED BY DISTRICT 1 SUPER TITLE DATE MAR 2 1982
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR - 1 1982

O.C.D.
HOBBS, N.J. 12