

9. 8-5/8" surface casing should be set in the Rustler Anhydrite formation cement circulated to the surface. If surface casing is set at a lesser depth, the 5-1/2" casing must be cemented from the casing shoe to the surface or cemented to the surface through a stage tool set at least 50 feet below the top of the Rustler, after cementing around the shoe with sufficient cement to fill to the base of the salt section.

RECEIVED

JUL 25 1978

CH. CONSERVATION COMM.
TUCSON, N. M.