Submit 3 Copies To Appropriate District	1	137 . 1 D		D ! 1 3 / 1. /	
Office District I	Energy, Minerals and	d Natural Resources	WELL API NO.	Revised March 2	23, 19
1625 N. French Dr., Hobbs, NM 87240	OH GONGEDN	A TOTAL TAXABLE AND A		5-26051	
District II 811 South First, Artesia, NM 87210		ATION DIVISION	5. Indicate Type		
District III		th Pacheco	STATE	FEE 🗷	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	•	NM 87505	6. State Oil & G		_
2040 South Pacheco, Santa Fe, NM 87505					
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	CES AND REPORTS O POSALS TO DRILL OR TO DE LICATION FOR PERMIT" (FOR	EEPEN OR PLUG BACK TO A	7. Lease Name o	r Unit Agreement Na	me:
1. Type of Well: Oil Well Gas Well	Other		MARK		
2. Name of Operator			8. Well No.		
Chevron U.S.A. Inc.			11	W/:11	
3. Address of Operator			9. Pool name or		
P.O. Box 1150, Midland, TX	79702		BLINEBRY (FRO	CAS) /WANTZ; ABO	
4. Well Location					
Unit Letter A:_	430 feet from the	NORTH line and	960 feet fr	rom the EAST	lir
Section 3		22S Range 37E	NMPM	County 11	EA
500000		whether DR, RKB, RT, GR	R, etc.)		
		3393′			
	Appropriate Box to Ir	ndicate Nature of Noti	ice, Report, or Oth	er Data	
NOTICE OF IN	TENTION TO:	S	UBSEQUENT RI	EPORT OF:	
PERFORM REMEDIAL WORK		N REMEDIAL WOF	RK [ALTERING CAS	ING
TEMPORARILY ABANDON	CHANGE PLANS		RILLING OPNS.	PLUG AND	_
	<u>-</u>		·	☐ PLUG AND ABANDONMEN	Т
	- -	COMMENCE DR	·	PLUG AND ABANDONMEN	Т
OTHER:	MULTIPLE COMPLETION	CASING TEST A CEMENT JOB OTHER: DBC	ND [ABANDONMEN	
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Complet of starting any proposed work or recompilation. 4/4/00 - 4/5/00 PORT 1/4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE	MULTIPLE COMPLETION eted Operations (Clearly st). SEE RULE 1103. For I W/PROD EQPT. TAGGED I 5343'-5494' W/300 SK LED CMT TO 5504'; CLE	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, an Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS: ANED OUT TO TOP OF RE	and give pertinent dates tach wellbore diagram to 500 PSI.	ABANDONMEN s, including estimated of proposed complete	date
OTHER: 12. Describe Proposed or Completed of Starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 1/4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILLE	MULTIPLE COMPLETION eted Operations (Clearly st). SEE RULE 1103. For It W/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEAR ED OVER STUCK PKR & PK	CASING TEST A CEMENT JOB OTHER: DRC tate all pertinent details, ar Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS: ANED OUT TO TOP OF RECUSHED DOWNHOLE TO 725	and give pertinent dates tach wellbore diagram to 500 PSI.	ABANDONMEN s, including estimated of proposed complete	date
OTHER: 12. Describe Proposed or Completor of starting any proposed work or recompilation. 4/4/00 - 4/5/00 PORT 4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRTG 4/12/00 - 4/13/00 MILLS 4/14/00 PERF	MULTIPLE COMPLETION eted Operations (Clearly st). SEE RULE 1103. For I W/PROD EQPT. TAGGED I 5343'-5494' W/300 SK LED CMT TO 5504'; CLE ED OVER STUCK PKR & PK ED 5342'-5926' W/2 JH	CASING TEST A CEMENT JOB OTHER: DRC tate all pertinent details, and Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TSI ANED OUT TO TOP OF REJUSTED DOWNHOLE TO 725' PF.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'.	ABANDONMEN i, including estimated i of proposed complete	date tion
OTHER: 12. Describe Proposed or Completed of Starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 1/4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILLE	MULTIPLE COMPLETION eted Operations (Clearly st). SEE RULE 1103. For I W/PROD EQPT. TAGGED I 5343'-5494' W/300 SK LED CMT TO 5504'; CLE ED OVER STUCK PKR & PK ED 5342'-5926' W/2 JH	CASING TEST A CEMENT JOB OTHER: DRC tate all pertinent details, and Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TSI ANED OUT TO TOP OF REJUSTED DOWNHOLE TO 725' PF.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'.	ABANDONMEN i, including estimated i of proposed complete	date tion
OTHER: 12. Describe Proposed or Completed of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 1/4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILLI 4/14/00 PERF. 4/17/00 - 4/20/00 ACZD	MULTIPLE COMPLETION eted Operations (Clearly step). SEE RULE 1103. For It w/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEAR CLED CMT TO 5504'; CLEAR C	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, an Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS. ANED CUT TO TOP OF RECUSHED DOWNHOLE TO 725' PF. 316 RCNB'S. SWARPED.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'.	ABANDONMEN i, including estimated i of proposed complete	date
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Complet of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 1/4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRTG 4/12/00 - 4/13/00 MILLS 4/14/00 PERF	MULTIPLE COMPLETION eted Operations (Clearly step). SEE RULE 1103. For It w/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEAR CLED CMT TO 5504'; CLEAR C	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, an Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS. ANED CUT TO TOP OF RECUSHED DOWNHOLE TO 725' PF. 316 RCNB'S. SWARPED.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'.	ABANDONMEN i, including estimated i of proposed complete	date tion
OTHER: 12. Describe Proposed or Completed of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 1/4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILLI 4/14/00 PERF. 4/17/00 - 4/20/00 ACZD	MULTIPLE COMPLETION eted Operations (Clearly step). SEE RULE 1103. For It w/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEAR CLED CMT TO 5504'; CLEAR C	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, an Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS. ANED CUT TO TOP OF RECUSHED DOWNHOLE TO 725' PF. 316 RCNB'S. SWARPED.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'.	ABANDONMEN i, including estimated i of proposed complete	date
OTHER: 12. Describe Proposed or Completed of Starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 1/4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILLI 4/14/00 PERF. 4/17/00 - 4/20/00 ACZD	MULTIPLE COMPLETION eted Operations (Clearly step). SEE RULE 1103. For It w/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEAR CLED CMT TO 5504'; CLEAR C	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, an Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS. ANED CUT TO TOP OF RECUSHED DOWNHOLE TO 725' PF. 316 RCNB'S. SWARPED.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'.	ABANDONMEN i, including estimated i of proposed complete	date
OTHER: 12. Describe Proposed or Completed of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 14/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILLI 4/14/00 PERF. 4/17/00 - 4/20/00 ACZD	MULTIPLE COMPLETION eted Operations (Clearly step). SEE RULE 1103. For It w/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEAR CLED CMT TO 5504'; CLEAR C	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, an Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS. ANED CUT TO TOP OF RECUSHED DOWNHOLE TO 725' PF. 316 RCNB'S. SWARPED.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'.	ABANDONMEN i, including estimated i of proposed complete	date
OTHER: 12. Describe Proposed or Complet of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 0 4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILE 4/14/00 PERF 4/17/00 - 4/20/00 ACZD RETURNED WELL TO PRODUCT	MULTIPLE COMPLETION eted Operations (Clearly st.). SEE RULE 1103. For It M/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEA ED OVER STUCK PKR & PK ED 5342'-5926' W/2 JHD W/15,000 GALS 15% & STUCK IN IN BLINEBRY GAS &	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, ar Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS: ANED OUT TO TOP OF RESISTED DOWNHOLE TO 725' PF. 316 RCNB'S. SWABBED.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/ 7'. RIH W/TBG TO 722	ABANDONMEN i, including estimated i of proposed complete	date
OTHER: 12. Describe Proposed or Completed of Starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 1/4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILLI 4/14/00 PERF. 4/17/00 - 4/20/00 ACZD	MULTIPLE COMPLETION eted Operations (Clearly st.). SEE RULE 1103. For It M/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEA ED OVER STUCK PKR & PK ED 5342'-5926' W/2 JHD W/15,000 GALS 15% & STUCK IN IN BLINEBRY GAS &	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, ar Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS: ANED OUT TO TOP OF RESISTED DOWNHOLE TO 725' PF. 316 RCNB'S. SWABBED.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/ 7'. RIH W/TBG TO 722	ABANDONMEN i, including estimated i of proposed complete	date tion
OTHER: 12. Describe Proposed or Complet of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 0 4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILE 4/14/00 PERF 4/17/00 - 4/20/00 ACZD RETURNED WELL TO PRODUCT	MULTIPLE COMPLETION eted Operations (Clearly st.). SEE RULE 1103. For It M/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEA ED OVER STUCK PKR & PK ED 5342'-5926' W/2 JHD W/15,000 GALS 15% & STUCK IN IN BLINEBRY GAS &	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, ar Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS. ANED OUT TO TOP OF REI DISHED DOWNHOLE TO 725' PF. 316 RCNB'S. SWAEBEED. E WANTZ; ABO.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/ 7'. RIH W/TBG TO 722	ABANDONMEN i, including estimated a of proposed complet REP. REP.	date tion
OTHER: 12. Describe Proposed or Complet of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 0 4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILE 4/14/00 PERF 4/17/00 - 4/20/00 ACZD RETURNED WELL TO PRODUCT	MULTIPLE COMPLETION eted Operations (Clearly st.). SEE RULE 1103. For It M/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEA ED OVER STUCK PKR & PK ED 5342'-5926' W/2 JHD W/15,000 GALS 15% & STUCK IN IN BLINEBRY GAS &	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, ar Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS: ANED OUT TO TOP OF RESISTED DOWNHOLE TO 725' PF. 316 RCNB'S. SWABBED.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/ 7'. RIH W/TBG TO 722	ABANDONMEN i, including estimated i of proposed complete	date tion
OTHER: 12. Describe Proposed or Completed of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR VA 4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITED WELL TO PRODUCE OF THE PROPOSED OF THE PROPOSE	MULTIPLE COMPLETION eted Operations (Clearly st.). SEE RULE 1103. For It W/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEA ED OVER STUK PER & PR ED 5342'-5926' W/2 JHD W/15,000 GALS 15% & 3 TION IN BLINEBRY GAS & Ove is true and complete to the	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, ar Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS. ANED OUT TO TOP OF REI DISHED DOWNHOLE TO 725' PF. 316 RCNB'S. SWAEBEED. E WANTZ; ABO.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'. RIH W/TBG TO 722 belief.	ABANDONMEN i, including estimated a of proposed complet REP. REP.	date tion
OTHER: 12. Describe Proposed or Completed of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POH 1/4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILLE 4/14/00 PERFORMED WELL TO PRODUCE RETURNED WELL TO PRODUCE SIGNATURE AND	MULTIPLE COMPLETION eted Operations (Clearly st.). SEE RULE 1103. For It W/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEA ED OVER STUK PER & PR ED 5342'-5926' W/2 JHD W/15,000 GALS 15% & 3 TION IN BLINEBRY GAS & Ove is true and complete to the	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, ar Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS. ANED OUT TO TOP OF REI DISHED DOWNHOLE TO 725' PF. 316 RCNB'S. SWAEBEED. E WANTZ; ABO.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'. RIH W/TBG TO 722 belief.	ABANDONMEN i, including estimated of proposed complete REP. RIH W/PMP & DATE	date tion
OTHER: 12. Describe Proposed or Complet of starting any proposed work or recompilation. 4/4/00 - 4/5/00 POR 0 4/6/00 - 4/7/00 SQZD 4/7/00 - 4/11/00 DRITE 4/12/00 - 4/13/00 MILE 4/14/00 PERF 4/17/00 - 4/20/00 ACZD RETURNED WELL TO PRODUCT	MULTIPLE COMPLETION eted Operations (Clearly st.). SEE RULE 1103. For It W/PROD EQPT. TAGGED IT 5343'-5494' W/300 SK LED CMT TO 5504'; CLEA ED OVER STUK PER & PR ED 5342'-5926' W/2 JHD W/15,000 GALS 15% & 3 TION IN BLINEBRY GAS & Ove is true and complete to the	CASING TEST A CEMENT JOB OTHER: DEC tate all pertinent details, ar Multiple Completions: At FILL @ 5569'. @ 1500 PSI; PRESS TS. ANED OUT TO TOP OF REI DISHED DOWNHOLE TO 725' PF. 316 RCNB'S. SWAEBEED. E WANTZ; ABO.	and give pertinent dates tach wellbore diagram TO TO 500 PSI. P @ 5585'. POH W/7'. RIH W/TBG TO 722 belief.	ABANDONMEN i, including estimated of proposed complete REP. RIH W/PMP & DATE	date tion