– Submit 3 Copies to Appropriate Dustrict Office	State of New Mexico	Form C-103 Revised 1-1-89
District Office <u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240 <u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088	WELL API NO. <u>30-025-26766</u> 5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM \$7410		6. Stato Oil & Gas Leaso No. V-3959
(DO NOT USE THIS FORM FOR PF	TICES AND REPORTS ON VELLS ROPOSALS TO DAILL OR TO DEEP IN OR PLUG BACK TO A ERVOIR. USE "APPLICATION FOR PERMIT" C-101) FOR SUCH PROPOSALS (7. Lease Name or Unit Agreement Name
1. Type of Well: OL OL OL WELL		Quay AQU State
2. Name of Operator		8. Well No.
YATES PETROLEUM CORPO	DRATION	9. Pool same or Wildcat
3. Address of Operator 105 South 4th St., Ar	testa NM 88210	Und. North Bell Lake Wolfcamp
Unit Letter <u>C</u> : <u>66</u> Section 10	50 Feet From The North Line and Township 23S Range 33E 7////////////////////////////////////	1980 Feet From The West Lea County
	3590.6' GR	
	k Appropriate Box to Indicate Nature of Notice NTENTION TO: S	UBSEQUENT REPORT OF:
NOTICE OF I	k Appropriate Box to Indicate Nature of Notice NTENTION TO: S PLUG AND ABANDON REMEDIAL WORK	
	NTENTION TO: S PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRIL	UBSEQUENT REPORT OF:
NOTICE OF II	NTENTION TO: S PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRIL CASING TEST AN	UBSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D CEMENT JOB
NOTICE OF II PERFORM REMEDIAL WORK	NTENTION TO: S PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRIL CASING TEST AN OTHER:_Perf	UBSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D CEMENT JOB
NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed O work) SEE RULE 1103. 5-17-97 - Rigged up with logging tools. (1 SPF - Delaware). packer and 2-7/8" t 10% iron control HC packer at 8801'. A control HCL acid. 5-18-97 - TIH with Set packer at 8801' 5-19-97 - Swabbed. 5-20-97 - Swabbed. gallons 25# borate sand. Pressured ou 5-21-97 - Bled well	NTENTION TO: S PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRUL CASING TEST AN CASING TEST AN OTHER: Performent duails, and give periment dues, wireline. TIH with logging tools a TIH with 4" casing guns and perfor TOOH with casing guns and rigged d ubing. Set RBP at 9022' and tested L acid. Pulled up and nippled down cidized perforations 8865-8882' with Released packer. TOOH with tubing a packer and 2-7/8" tubing. Nippled d . Tested packer to 1500 psi. Swabb Shut well in. Frac'd perforations 8865-8882' (via crosslink gel, 40000# 20-40 Ottawa so it to 5000# with 28 bbls flush. Shut down. Nippled down tree. Nippled	UBSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D CEMENT JOB Drate, acidize & frac including estimated date of starting any proposed and ran CBL/GR/CCL log. TOOH ated 8865-8882' w/18 .42" holes own wireline. TIH with RBP, to 2000 psi. Spotted 2 bbls BOP. Nippled up tree. Set 1500 gallons 10% iron nd packer. Shut down. own BOP. Nippled up tree. ed. Shut well in. 2-7/8" tubing) with 15500 and and 9000# 16-30 Super LC in. up BOP. Pressured annulus to
NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed O work) SEE RULE 1103. 5-17-97 - Rigged up with logging tools. (1 SPF - Delaware). packer and 2-7/8" t 10% iron control HC packer at 8801'. A control HCL acid. 5-18-97 - TIH with Set packer at 8801' 5-19-97 - Swabbed. 5-20-97 - Swabbed. 5-21-97 - Bled well. Thereby certify that the information show	NTENTION TO: S PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRUL CASING TEST AN CASING TEST AN OTHER: Perf. Perations (Clearly state all perimens details, and give perimens dates, wireline. TIH with logging tools a TIH with 4" casing guns and perfor TOOH with casing guns and rigged d ubing. Set RBP at 9022' and tested L acid. Pulled up and nippled down cidized perforations 8865-8882' with Released packer. TOOH with tubing a packer and 2-7/8" tubing. Nippled d . Tested packer to 1500 psi. Swabb Shut well in. Frac'd perforations 8865-8882' (via crosslink gel, 40000# 20-40 Ottawa so it to 5000# with 28 bbls flush. Shut I down. Nippled down tree. Nippled	UBSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D CEMENT JOB Drate, acidize & frac Drate, acidize & frac Drate
NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed O work) SEE RULE 1103. 5-17-97 - Rigged up with logging tools. (1 SPF - Delaware). packer and 2-7/8" t 10% iron control HC packer at 8801'. A control HCL acid. 5-18-97 - TIH with Set packer at 8801' 5-19-97 - Swabbed. 5-20-97 - Swabbed. gallons 25# borate sand. Pressured ou 5-21-97 - Bled well	NTENTION TO: S PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRIL CASING TEST AN CASING TEST AN OTHER: Perfor perations (Clearly state all perimens details, and give perimens dates, wireline. TIH with logging tools a TIH with 4" casing guns and perfor TOOH with casing guns and rigged d ubing. Set RBP at 9022' and tested L acid. Pulled up and nippled down cidized perforations 8865-8882' with Released packer. TOOH with tubing a packer and 2-7/8" tubing. Nippled d . Tested packer to 1500 psi. Swabb Shut well in. Frac'd perforations 8865-8882' (via crosslink gel, 40000# 20-40 Ottawa s it to 5000# with 28 bbls flush. Shut I down. Nippled down tree. Nippled . Tested complete to the best of my throwtedge and belief. Multipled down tree. Nippled	UBSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D CEMENT JOB Drate, acidize & frac including estimated date of starting any proposed and ran CBL/GR/CCL log. TOOH ated 8865-8882' w/18 .42" holes own wireline. TIH with RBP, to 2000 psi. Spotted 2 bbls BOP. Nippled up tree. Set 1500 gallons 10% iron nd packer. Shut down. own BOP. Nippled up tree. ed. Shut well in. 2-7/8" tubing) with 15500 and and 9000# 16-30 Super LC in. up BOP. Pressured annulus to CONTINUED ON NEXT PAGE:
NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 5-17-97 - Rigged up with logging tools. (1 SPF - Delaware). packer and 2-7/8" t 10% iron control HC packer at 8801'. A control HCL acid. 5-18-97 - TIH with Set packer at 8801' 5-19-97 - Swabbed. 5-20-97 - Swabbed. 5-21-97 - Bled well. I hereby cerufy that the information above SIONATURE	NTENTION TO: S PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COMMENCE DRIL CASING TEST AN CASING TEST AN OTHER: Perfor perations (Clearly state all perimens details, and give perimens dates, wireline. TIH with logging tools a TIH with 4" casing guns and perfor TOOH with casing guns and rigged d ubing. Set RBP at 9022' and tested L acid. Pulled up and nippled down cidized perforations 8865-8882' with Released packer. TOOH with tubing a packer and 2-7/8" tubing. Nippled d . Tested packer to 1500 psi. Swabb Shut well in. Frac'd perforations 8865-8882' (via crosslink gel, 40000# 20-40 Ottawa s it to 5000# with 28 bbls flush. Shut I down. Nippled down tree. Nippled . Tested complete to the best of my throwtedge and belief. Multipled down tree. Nippled	UBSEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D CEMENT JOB Drate, acidize & frac including estimated date of starting any proposed and ran CBL/GR/CCL log. TOOH ated 8865-8882' w/18 .42" holes own wireline. TIH with RBP, to 2000 psi. Spotted 2 bbls BOP. Nippled up tree. Set 1500 gallons 10% iron nd packer. Shut down. own BOP. Nippled up tree. ed. Shut well in. 2-7/8" tubing) with 15500 and and 9000# 16-30 Super LC in. up BOP. Pressured annulus to CONTINUED ON NEXT PAGE: ns Technician DATE May 29, 199

-