

Budget Bureau No. 1004—
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT..." for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Conoco Inc.		8. FARM OR LEASE NAME Dauenger A-8	
3. ADDRESS OF OPERATOR P.O. Box 460 - Holms, NYM 88240		9. WELL NO. #4	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2310' FNL + 810' FEL		10. FIELD AND POOL OR WILDCAT Jalmet Yates 7 Bros. Tr	
14. PERMIT NO. 30-025-26889		11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA Sec. 8, T. 23S, R. 30E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3485' DF		12. COUNTY OR PARISH Lea	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data		13. STATE NYM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE.

ABANDON®

REPAIR WELL

CHANGE PLANS

1996b,c]

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Notify BLM Office in Hobbs

MIRU. ND wellhead. NU BOP. Set CIBP @ 3300'. Spot 25 sx cmt. on CIBP. Pump 10 bbls water, 18 sx cmt., 4 bbl water + displace with 4 bbls mud to spot cmt plug from 1442' to 1620'. WOC Pump 25 sx cmt., establishing circulation to set surface plug. ND BOP, cut off csq. 1 fill csq. w/cmt to surface. Erect P+A marker. Restore location.

18. I hereby certify that the foregoing is true and correct

SIGNED W.W. Baker W.W. Baker TITLE Administrative Supervisor DATE Sept. 29, 1989

(This space for Federal or State office use)

APPROVED BY *Cong. Secretary Shannon L. Shaw*

TITLE PETROLEUM ENGINEER

DATE 10 23 59

CONDITIONS OF APPROVAL, IF ANY:

***See Instructions on Reverse Side**