

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27185
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Grizzell
8. Well No. 3
9. Pool name or Wildcat Eunice San Andres west

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Zia Energy, Inc.	
3. Address of Operator P.O. Box 2219, Hobbs, NM 88240	
4. Well Location Unit Letter 0 : 330 Feet From The South Line and 1650 Feet From The East Line Section 5 Township 22 South Range 37 East NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3424' GR - 3438' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Plug back & recomplete <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

1. Rigged up Eunice Well Service. Installed BOP & Stripper head.
2. Pulled rods, pump and tubing.
3. Set a CIBP at 4511' RKB on tubing. Pumped 20' of cement on CIBP. Abandon Drinkard Perforations.
4. Complete to produce the San Andres formation in the interval between 3950' and 4050'.
5. Re-run tubing, pump and rods. Remove BOP and stripper head. Placed on pump to produce and test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Farris Nelson TITLE Engineer DATE 11/12/90

TYPE OR PRINT NAME Farris Nelson 505/393-2937 TELEPHONE NO.

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

ZA Drinkard E

RECEIVED

NOV 16 1990

NOV 16 1990
NOV 16 1990
NOV 16 1990