

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI-DATE
(Other instruction on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Mobil Producing TX & NM Inc.		8. FARM OR LEASE NAME Tristi Draw Federal
3. ADDRESS OF OPERATOR Mobil Exploration & Producing U.S. Inc. P.O. Box 633, Midland, TX 79702		9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 FSL 2480 FEL		10. FIELD AND POOL, OR WILDCAT Daimondtail-bone Spring
14. PERMIT NO.		11. SEC., T., R., M., OR BLM, AND SURVEY OR AREA Sec. 14, T-23S, R-32E
15. ELEVATIONS (Show whether SP, ST, OR, etc.) GI - 3706		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

Plug & Abandon

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS* (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Notify NMOCD & BLM 24 hrs. prior to MIRU.
2. POH w/rods, pump & tbq.
3. Set CIBP @ 9460 & cap w/35x cmt.
4. Cut 7 5/8 csg. @ 6500. Pull csg. from well.
5. Set cmt plug from 6550 - 6400. [TAG]
6. Set cmt plug from 4950 - 4800 [TAG] (SJK)
7. Set cmt plug from 710 - 610
8. Set cmt plug from 50 - 0
9. Cut off csg. Weld on a steel plate w/P&A marker which meets NMOCD/BLM requirements.
10. Cover pits and clean location per BLM/MNOCD requirements.

18. I hereby certify that the foregoing is true and correct

SIGNED

Shelby Ladd

TITLE

Mobil Exploration & Producing U.S. Inc.
as Agent for Mobil Producing TX & NM Inc.

DATE 5-16-89

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

FOR:
TITLE

DATE

5-25-89

*See Instructions on Reverse Side