## State of New Mexico

Form C	-103
Revised	1-1-89

	Energy, 1		sources Department		Revised 1-1-39
District Office	OTI (	CONSERVATIO	NOTITITION		
2.0. Box 1980, Hobbs, NM	\$1240 · OIL (	P.O. Box 208		WELL API NO.	_
ISTRICT II	Sa	anta Fe, New Mexico			25 28512
O. Drawer DD, Artesia, NA	A 84210	•		5. Indicate Type of Lease	TATE X FEE
ISTRICT III 000 Rio Brazos Rd., Azisc, I	NM \$7410			6. State Oil & Gas Lease	
		D REPORTS ON WEL			
	RENT RESERVOIR. US	O DRILL OR TO DEEPEN E "APPLICATION FOR PEI SUCH PROPOSALS.)		7. Lease Name or Unit A	greenent Name
Type of Well:	aus 🗆				
MET []	MET	onex Injecti	on Well	State A AC 1	
Name of Operator Clayton Williams	Fnergy Inc		•	8. Well No.	••
Address of Operator	Liter gy, The.		······································	9. Pool name or Wildcat	
Six Desta Drive,	Suite 3000 Mi	dland, Texas 79705		Langlie Mattix 7	'Rvrs Queen GB
Well Location				· ···	
Unit LetterK	:1345 Feet Fr	room The West	Line and1	395 Feet From The _	South Lin
Section	3 Towns	hin 23S Ra	nge 36E	NMPM Lea	County
		10. Elevation (Show whether	<del>- g -</del>	VII	
	<u> </u>	GR - 3	<del></del>		
	Check Appropri	ate Box to Indicate l	Nature of Notice, R	eport, or Other Dat	<b>a</b> .
NOTIC	E OF INTENTIO	NTO:	· SUB	SEQUENT REPO	ORT OF:
RFORM REMEDIAL WO	RK PLUC	AND ABANDON	REMEDIAL WORK	ALTE	RING CASING
		G AND ABANDON	REMEDIAL WORK		RING CASING [
MPORARILY ABANDON				G OPNS. PLUG	_
MPORARILY ABANDON			COMMENCE DRILLING	G OPNS. PLUG	AND ABANDONMENT
MPORARILY ABANDON ILL OR ALTER CASING THER:	CHAI		COMMENCE DRILLING CASING TEST AND CO	S OPNS. PLUG	AND ABANDONMENT
MPORARILY ABANDON  ILL OR ALTER CASING  THER:  2. Describe Proposed or Cox  work) SEE RULE 1103.	CHAI	NGE PLANS	COMMENCE DRILLING CASING TEST AND CO	S OPNS. PLUG	AND ABANDONMENT
MPORARILY ABANDON  ILL OR ALTER CASING  THER:  2. Describe Proposed or Cor  work) SEE RULE 1103.  03/27/97	CHAI	NGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: Tempora d give pertinent dates, inclu	S OPNS. PLUG	AND ABANDONMENT
MPORARILY ABANDON  JLL OR ALTER CASING  THER:  2. Describe Proposed or Corwork) SEE RULE 1103.  03/27/97  1) Loaded 5-1/2"	mpleted Operations (Clearly	y state all persinent details, an	COMMENCE DRILLING CASING TEST AND CE OTHER: Tempora d give pertinent dates, inclu	SOPNS. PLUG	AND ABANDONMENT
MPORARILY ABANDON  JLL OR ALTER CASING  THER:  2. Describe Proposed or Corwork) SEE RULE 1103.  03/27/97  1) Loaded 5-1/2"	chai	NGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: Tempora d give pertinent dates, inclu	SOPNS. PLUG	AND ABANDONMENT
MPORARILY ABANDON LL OR ALTER CASING HER:  Describe Proposed or Cox work) SEE RULE 1103.  03/27/97  1) Loaded 5-1/2"  2) Pressure test (Chart attach	chai	y state all persisent details, and all t water. (CIBP @ 3)	COMMENCE DRILLING CASING TEST AND CE OTHER: Tempora d give pertinent dates, inclu	SOPNS. PLUG	AND ABANDONMENT
MPORARILY ABANDON  ILL OR ALTER CASING  THER:  2 Describe Proposed or Cox work) SEE RULE 1103.  03/27/97  1) Loaded 5-1/2"  2) Pressure test (Chart attach	chai	y state all persisent details, and all t water. (CIBP @ 3)	COMMENCE DRILLING CASING TEST AND CE OTHER: Tempora d give pertinent dates, inclu	SOPNS. PLUG	AND ABANDONMENT
MPORARILY ABANDON  ILL OR ALTER CASING  THER:  2. Describe Proposed or Cox work) SEE RULE 1103.  03/27/97  1) Loaded 5-1/2"  2) Pressure test (Chart attach	chai	y state all persisent details, and all t water. (CIBP @ 3)	COMMENCE DRILLING CASING TEST AND CO OTHER: Tempora d give pertinent dates, inclu  550') O psi for 30 minute	EMENT JOB I	AND ABANDONMENT
CMPORARILY ABANDON  JLL OR ALTER CASING  THER:  2 Describe Proposed or Cox work) SEE RULE 1103.  03/27/97  1) Loaded 5-1/2"  2) Pressure test (Chart attach	chai	y state all persisent details, and all t water. (CIBP @ 3)	COMMENCE DRILLING CASING TEST AND CO OTHER: Tempora d give pertinent dates, inclu  550') O psi for 30 minute	EMENT JOB I	AND ABANDONMENT
03/27/97  1) Loaded 5-1/2"  2) Pressure test (Chart attach	chai	y state all persisent details, and all t water. (CIBP @ 3)	COMMENCE DRILLING CASING TEST AND CO OTHER: Tempora d give pertinent dates, inclu  550') O psi for 30 minute	EMENT JOB I	AND ABANDONMENT
EMPORARILY ABANDON  JLL OR ALTER CASING  THER:  2. Describe Proposed or Cox work) SEE RULE 1103.  03/27/97  1) Loaded 5-1/2"  2) Pressure test (Chart attach	chai	y state all persisent details, and all t water. (CIBP @ 3)	COMMENCE DRILLING CASING TEST AND CO OTHER: Tempora d give pertinent dates, inclu  550') O psi for 30 minute	SOPNS. PLUG	AND ABANDONMENT
MPORARILY ABANDON  ILL OR ALTER CASING  THER:  2 Describe Proposed or Cox work) SEE RULE 1103.  03/27/97  1) Loaded 5-1/2"  2) Pressure test (Chart attach	chai	y state all persisent details, and all t water. (CIBP @ 3)	COMMENCE DRILLING CASING TEST AND CO OTHER: Tempora d give pertinent dates, inclu  550') O psi for 30 minute	EMENT JOB I	AND ABANDONMENT
MPORARILY ABANDON OLL OR ALTER CASING THER:  2. Describe Proposed or Corwork) SEE RULE 1103.  03/27/97  1) Loaded 5-1/2"  2) Pressure test (Chart attach 3) Temporarily a	casing w/field sated casing from sured)	y state all persisent details, and all t water. (CIBP @ 3)	COMMENCE DRILLING CASING TEST AND CO OTHER: Tempora of give pertinent dates, included  550') O psi for 30 minute  This Approx Abandonment	EMENT JOB I	AND ABANDONMENT

(This space for State Use) ORIGINAL SIGNAD BY JERRY SEXTON (SETTING) BY JERRY SEXTON APR 04 1397 APPROVED BY-