	El recente P. C	FSA and the second	OR verse side)	5. LEASE DES	IGNATION AND BERIAL NO.	
BUREAU OF HOBES MANAGEMENT					NM 03326	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)					ALLOTTEE OR TRIBE NAM	
				7. UNIT AGREE	7. UNIT AGREEMENT NAME	
WELL X WELL	OTHER					
Tempo Energy, Inc.					8. FARM OR LEASE NAME	
8. ADDRESS OF OPERATOR				9. WELL NO.	Payne Federal 9. Will No.	
4000 N. Big Sprin	ng, Suite 109,	Midland, TX	79705	5		
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.[*] See also space 17 below.) At surface 					10. FIELD AND POOL, OF WILDCAT Triste Draw	
1650' FNL & 1650	' FWL of Sec. 3	35, T238, R321	E	11. BRC., T., R. SURVBY	, M., OR BLE. AND OR AREA	
4. PERMIT NO. 15. ELEVATIONS (Ebow whether D7, RT, GL, etc.)					, T23S, R32E	
Approved 7-11-85		' GR, 3684' KI			PARISH 18. STATE	
······································				Lea	NM	
		iox to Indicate No	ature of Notice, Report, a	or Other Data		
NOTIC	E OF INTENTION TO :		RUE	BEQUENT REFORT OF:	:	
TEST WATER BHUT-OFF	PULL OR ALTER	R CASING	WATER SHUT-OFT	EEP.	AIRING WELL	
PRACTUBE TREAT	MULTIPLE COM	PLETE	FRACTURE TREATMENT	ALT	ERING CABING	
RIDOT OR ACIDIZE	ABANDON*		BEOOTING OR ACIDIZING	ABAT	NDONMENT* XX	
(Other)	CHANGE PLANS		(Other)	ults of multiple com	pletion on Well	
nent to this work.)* In accorda	nce with verba		details. and give pertinent days and measured and true ve ven by Mr. Bob Pit	theat deptas for an	ited date of starting an markers and gones perti	
nent to this work.)• In accorda plugged as	nce with verba	l approval gi	details, and give pertinent day ons and measured and true ve ven by Mr. Bob Pit	tes, including estima rtical depths for all	ited date of starting an markers and gones perti	
In accorda plugged as 1. Set 1s 2. Set 2n	ance with verba 5 follows: 5t plug from 46 6d plug from 26	l approval gi 00' to 4500', 00' to 2500',	details, and give pertinent de ons and measured and true ve ven by Mr. Bob Pit WOC 4 hours. WOC 4 hours.	tes, including estima rtical depths for all Schke, the w	nted date of starting an markers and somes perti- vell was	
In accorda plugged as 1. Set 1s 2. Set 2n 3. Set 3r top of	ance with verba 5 follows: 5t plug from 46 6d plug from 26 7d plug from 11	1 approval gi 00' to 4500', 00' to 2500', 50' to 1050', sing and erre	 details. and give pertinent dependent of the second measured and true verse wen by Mr. Bob Pit WOC 4 hours. WOC 4 hours. spotted 10 sacks cted the plug and 	of coment in	the	
In accorda plugged as 1. Set 1s 2. Set 2n 3. Set 3r top of	ance with verba s follows: at plug from 46 ad plug from 26 d plug from 11 the 9 5/8" cas ed and Abandone	1 approval gi 00' to 4500', 00' to 2500', 50' to 1050', sing and erre	 details. and give pertinent dependent of the second measured and true verse wen by Mr. Bob Pit WOC 4 hours. WOC 4 hours. spotted 10 sacks cted the plug and 	of coment in	the	
In accorda plugged as 1. Set 1s 2. Set 2n 3. Set 3r top of Plugge	ance with verba s follows: at plug from 46 ad plug from 26 d plug from 11 the 9 5/8" cas ed and Abandone	1 approval gi 00' to 4500', 00' to 2500', 50' to 1050', sing and erre	details. and give pertinent da ons and measured and true ve ven by Mr. Bob Pit WOC 4 hours. WOC 4 hours. spotted 10 sacks cted the plug and Final Report.	of coment in	the	
In accorda plugged as 1. Set 1s 2. Set 2n 3. Set 3r top of Plugge	nce with verba follows: it plug from 46 id plug from 26 id plug from 11 the 9 5/8" can ed and Abandone	1 approval gi 00' to 4500', 00' to 2500', 50' to 1050', sing and erre- ed 8-14-85. I	details. and give pertinent da ons and measured and true ve ven by Mr. Bob Pit WOC 4 hours. WOC 4 hours. spotted 10 sacks cted the plug and Final Report.	of cement in abandon mark	the er.	

4A

RECEIVED AUG 2' 1985 HOB S OFFICE

.

-