

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on  
reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 03326

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Payne Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Triste Draw

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 35, T23S, R32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. NAME OF OPERATOR  
Tempo Energy, Inc.  
3. ADDRESS OF OPERATOR  
4000 N. Big Spring, Suite 109, Midland, TX 79705  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1650' FNL & 1650' FWL of Sec. 35, T23S, R32E  
14. PERMIT NO.  
Approved 7-11-85  
15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3671.4' GR., 3684' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☒ XX  
REPAIR WELL ☐ CHANGE PLANS ☐  
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☐  
(Other) ☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Verbal directions given by Mr. Bob Pitschke for intent to  
plug and abandon as follows:

1. Set 1st plug from 4600' to 4500', WOC 4 hours.
2. Set 2nd plug from 2600' to 2500', WOC 4 hours.
3. Set 3rd plug from 1150' to 1050', <sup>Tag</sup> and spot 10 sacks of cement in the top of the 9 5/8" casing and erect the plug and abandon marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE 8-14-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 12-13-85

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

RECEIVED  
DEC 16 1985  
O.C.C.  
HOBBES OFFICE