		w Mexico Off Conservation Bayes in calanda 1625 N. French Drive	
form 3160-5 June 1990) Do not us	DEPARTMEN BUREAU OF SUNDRY NOTICES se this form for proposals to dri	Hobbs, NM 200.00 TED STATES NT OF THE INTERIOR LAND MANAGEMENT AND REPORTS ON WELLS ill or to deepen or reentry to a different reservoir OR PERMIT-" for such proposals	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM-98191 6. If Indian, Allottee or Tribe Name
		IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of We Oil	ell		8. Well Name and No.
2. Name of O			
	Producing_Company		Aracanga Federal #1 9. API Well No.
3. Address ar	nd Telephone No.	·····	30-025-31650
P. O.	Box 10340, Midland, TX	79702-7340 (915)685-8100	10. Field and Pool, or Exploratory Area
4. Location of	f Well (Footage, Sec., T., R., M., or Survey De	scription)	Wildcat Delaware
			11. County or Parish, State
330' F	SL & 2310' FEL, Section	4, T23S, R32E	
			Lea County, NM
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, C	OR OTHER DATA
	TYPE OF SUBMISSION	TYPE OF ACTION	
	Notice of Intent	Abandonment	Change of Plans
		Recompletion	
	🕅 Subsequent Report	Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off
	Final Abandonment Notice	Attering Casing	
			Conversion to Injection
		Other <u>Add Perfs</u>	Dispose Water
13. Describe	Proposed or Completed Operations (Clearty s	Other <u>Add Perfs</u> tate all pertinet details, and give pertinent dates, including estimated date	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is
directiona 99/26/00 99/27/00 99/28/00 99/30/00 0/03/00 0/04/00 0/05/00 0/12/00 0/13/00 0/14/00 0/15/00 0/15/00 0/17/00 0/18/00	Alty drilled, give subsurface locations and mease Acdz 8302-8314 w/ 1000 gals 7- Perf Delaware 8047-8059 w/ 2 s Rel RBP @ 8210 & PUH to 7964 Perf Delaware 7882-7888 w/ 2 s Rel RBP @ 7964. Pull RBP to 7 Acdz 7409-28 w/ 1000 gals 7-1/2 Rel RBP @ 7650. PUH & set @ Perf Delaware 6919-22 & 6950-4 Acdz 6919-22, 6950-60, 6972-80 Rel RBP @ 7241 & POH. TIH w Frac 6919-22 & 6950-60 w/ 22,5	□ otherAdd_Perfs	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* 0000 gals 7-1/2% acid. 28 w/ 2 spf. 4 7008-14 w/ 2 spf.
directiona 9/26/00 9/27/00 9/28/00 9/30/00 0/03/00 0/04/00 0/05/00 0/12/00 0/12/00 0/12/00 0/12/00 0/13/00 0/14/00 0/15/00 0/17/00 0/18/00 0/20/00	Alty drilled, give subsurface locations and mease Acdz 8302-8314 w/ 1000 gals 7- Perf Delaware 8047-8059 w/ 2 s Rel RBP @ 8210 & PUH to 7964 Perf Delaware 7882-7888 w/ 2 s Rel RBP @ 7964. Pull RBP to 7 Acdz 7409-28 w/ 1000 gals 7-1/2 Rel RBP @ 7650. PUH & set @ Perf Delaware 6919-22 & 6950-60 Acdz 6919-22, 6950-60, 6972-80 Rel RBP @ 7241 & POH. TIH w Frac 6919-22 & 6950-60 w/ 22,5 Catch & rel RBP @ 6966.	OtherAddPerfs	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* 000 gals 7-1/2% acid. 28 w/ 2 spf. 27008-14 w/ 2 spf. EPTED FOR RECORD OCT 2 8 2002 GARY GOURLEY ROCEUM ENGINEER
directiona 99/26/00 99/27/00 99/28/00 99/30/00 0/03/00 0/04/00 0/05/00 0/12/00 0/12/00 0/12/00 0/12/00 0/15/00 0/14/00 0/15/00 0/14/00 0/15/00 0/14/00 0/14/00 0/14/00 0/12/00	Set CIBP @ 8500'. Perf Delawa Acdz 8302-8314 w/ 1000 gals 7- Perf Delaware 8047-8059 w/ 2 s Rel RBP @ 8210 & PUH to 7964 Perf Delaware 7882-7888 w/ 2 s Rel RBP @ 7964. Pull RBP to 7 Acdz 7409-28 w/ 1000 gals 7-1/2 Rel RBP @ 7650. PUH & set @ Perf Delaware 6919-22 & 6950-1 Acdz 6919-22, 6950-60, 6972-81 Rel RBP @ 7241 & POH. TIH w Frac 6919-22 & 6950-60 w/ 22,5 Catch & rel RBP @ 6966. Put well on production.	□ otherAdd_Perfs	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* 0000 gals 7-1/2% acid. 28 w/ 2 spf. 27008-14 w/ 2 spf. EPTED FOR RECORD OCT 2 8 2002 GARYGOURLEY
directiona 9/26/00 9/27/00 9/28/00 9/28/00 0/03/00 0/05/00 0/12/00 0/12/00 0/13/00 0/14/00 0/15/00 0/17/00 0/17/00 0/17/00 0/17/00 0/17/00 0/17/00 14. I hereby- Signed (This space	Set CIBP @ 8500'. Perf Delawa Acdz 8302-8314 w/ 1000 gals 7- Perf Delaware 8047-8059 w/ 2 s Rel RBP @ 8210 & PUH to 7964 Perf Delaware 7882-7888 w/ 2 s Rel RBP @ 7964. Pull RBP to 7 Acdz 7409-28 w/ 1000 gals 7-1/2 Rel RBP @ 7650. PUH & set @ Perf Delaware 6919-22 & 6950-6 Acdz 6919-22, 6950-60, 6972-8 Rel RBP @ 7241 & POH. TIH w Frac 6919-22 & 6950-60 w/ 22,5 Catch & rel RBP @ 6966. Put well on production.	□ otherAdd_Perfs	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* 000 gals 7-1/2% acid. 28 w/ 2 spf. 2 7008-14 w/ 2 spf. SPTED FOR RECORD OCT 2 8 2002 CARYGOURLEY TROCEUM ENGINEER Date 10/10/02
directiona 9/26/00 9/27/00 9/28/00 9/28/00 0/03/00 0/03/00 0/05/00 0/12/00 0/12/00 0/13/00 0/14/00 0/15/00 0/17/00 0/15/00 0/17/00 0/17/00 0/18/00 0/20/00	Set CIBP @ 8500'. Perf Delawa Acdz 8302-8314 w/ 1000 gals 7- Perf Delaware 8047-8059 w/ 2 s Rel RBP @ 8210 & PUH to 7964 Perf Delaware 7882-7888 w/ 2 s Rel RBP @ 7964. Pull RBP to 7 Acdz 7409-28 w/ 1000 gals 7-1/2 Rel RBP @ 7650. PUH & set @ Perf Delaware 6919-22 & 6950-6 Acdz 6919-22, 6950-60, 6972-8 Rel RBP @ 7241 & POH. TIH w Frac 6919-22 & 6950-60 w/ 22,5 Catch & rel RBP @ 6966. Put well on production.	OtherAddPerfs	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* 000 gals 7-1/2% acid. 28 w/ 2 spf. 27008-14 w/ 2 spf. EPTED FOR RECORD OCT 2 8 2002 GARY GOURLEY ROCEUM ENGINEER

GWW

5 5 5