

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)
30-025-31751
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT
8. Well No. 215
9. Pool name or Wildcat ARROWHEAD / GB
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3417 GE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator CHEVRON U.S.A. INC.
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>7</u> Township <u>22S</u> Range <u>37E</u> NMPM <u>LEA</u> County

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <u>DRILLING SUMMARY</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

MIRU ROD-RIC # 4 ON 11-1-92.
SPUD 12.25" HOLE, DRILL AND SURVEY TO 1070'.
RUN 8 5/8" CASING TO 1070', PUMP 750 SX. OF CEMENT AND CIRCULATE 150 SX. TO SURFACE.
WAIT ON CEMENT FOR 12.5 HOURS, DRILL OUT FLOAT AND CMT TO SHOE, TEST CSG TO 1000#-OK.
DRILL AND SURVEY 7 7/8" HOLE TO 3868'.
RUN 5.5" CASING TO 3868', PUMP 800 SX. CEMENT AND CIRCULATE 138 SX. TO SURFACE.
INSTALL WELLHEAD AND TEST.
RELEASE RIG ON 11-7-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. Matthews TITLE TECH. ASSISTANT DATE: 11-9-92

TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO. (915)687-7812

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE NOV 13 '92

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 12 1992

OCD HOBBS OFFICE