	NT OF THE INTERIOR	P.O. BOX 19 HORBS. NEY	80 / MEM QOR 348 Nudget Bureau No. 100 Expires: March 31, 1	4-0135
SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Designation and Serial No.	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT " for such proposals			LC-032 Alottee or Tribe Name	
		7. If Unit or C	A, Agreement Desig	nation
1. Type of Well: OIL GAS WELL		8. Well Name	and Number	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.			BLINEBRY, A.H. FEDERAL NCT-1	
3. Address and Telephone No.			45	
4. Location of Well (Footage, Sec., T., R., M., or Sur		97-0442 9. API Well N	o. 30 025 32673	
the fit as		10. Field and From The Tubb Oil and (Pool, Exploaratory An	6a
	Township <u>22-S</u> Range <u>38-E</u>		LEA , NM	
12. Check Appropriate E	Box(s) To Indicate Nature of N	Notice, Report. or Ot	her Data	
TYPE OF SUBMISSION		TYPE OF ACTIO		
 Notice of Intent Subsequent Report Final Abandonment Notice 	Abandonment Recompletion Plugging Back Casing Repair Atlering Casing OTHER:		Change of Plans New Construction Non-Routine Fract Water Shut-Off Conversion to Inje Dispose Water as: Report needs of multiple of	turing oction
 work. If well is directionally drilled, give subsurfactions (clean work. If well is directionally drilled, give subsurfactions) (clean work. If well is directionally drilled, give subsurfactions) (clean work. If well is directionally drilled, give subsurfactions) (clean work. If well is directionally drilled, give subsurfactions) (clean work. If well is directionally drilled, give subsurfactions) (clean work. If well is directionally drilled, give subsurfactions) (clean work. If well is directionally drilled, give subsurfactions) (clean work. If well is directionally drilled, give subsurfactions) (clean work. If well is directionally drilled, give subsurfactive) (clean well) (clean well with CIBP and set (g) 6700'. Tested C 3. Perforate Tubb Oil and Gas zone on interval 6096 (clean well) (clean well and Gas zone on interval 6096 (clean well) (clean well with 4000g 15% NEFE HCL + ballseales) (clean well back. Paesase packer and TOH. TH with production equipment and place on pume (clean well) (clean well)	Drinkard-Abo completion and perforate upł y downhole commingle production from the Install BOP. IBP w/2000# 5'-6258' with 2 jspf, 150 shots. ers. TIH, ND BOP, install wellhead.), with 47500g gel +153000# 20/40 sand, 4	nole into the Tubb Oil and Ga Drinkard-Abo and the Tubb		
	Ensinger	stant	DATE	4/30/96
A. I hereby certify that the forgeting is true and correct SIGNATURE THE HERE HERE YPE OR PRINT NAME Paula S. IVI This space for Federal or Sizes office use)	TITLE Engineering Assis			
SIGNATURE Quile the Signature Paula S. IV			DATE	

5

