to Appropriate District Office	Energy,	nerals and Natural R	esources Department	Form C-103 Revised 1-1-89
DISTRICT I	OIL CO	) NSERVATIO	ON DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	_	P.O. Box 20		30-025-33000
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Sant	a Fe, New Mexico	87504-2088	5. Indicate Type of Lease
DISTRICT III	10			STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 8741	10			VA-971
( DO NOT USE THIS FORM FOR I DIFFERENT RES	PROPOSALS TO L	APPLICATION FOR PE	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL AND WELL AND WELL				
well         X         well            2.         Name of Operator   <	<u></u>	OTHER		San Simon Unit
YATES PETROLEUM CORP	ORATION			1
				9. Pool name or Wildcat San Simon Sink Morroy (and)
4. Well Location				San Simon Sink Morrow (gas)
II. Chec NOTICE OF II	k Appropriate		GR Nature of Notice, R	eport, or Other Data SEQUENT REPORT OF:
	PLUG AN		REMEDIAL WORK	
	CHANGE	PLANS		GOPNS. DPLUG AND ABANDONMENT
ULL OR ALTER CASING	]		CASING TEST AND CE	
THER: Acidize existing	g perfs	x x		
			OTHER:	
DTHER: Acidize existin 12. Describe Proposed or Completed Op work) SEE RULE 1103. Propose to acidize p	perations (Clearly sta	te all pertinent details, an	OTHER:	ting estimated date of starting any proposed
<ul> <li>12. Describe Proposed or Completed Op work) SEE RULE 1103.</li> <li>Propose to acidize p</li> <li>1. Pressure tubing</li> <li>2. Acidize with 300 acid w/1750 scf/bbl plugs dividing the a</li> <li>30 bbls 3% KCL wates</li> <li>3. Flange in coiled ended coiled tubing</li> </ul>	erations (Clearly sta perforation annulus to 00 gallons N2. Utili acid in thr r with 3000 d tubing ha with pump et slips. et nozzle a on. Flow t	te all periment details, and s 13582-13711 2000 psi and 10% iron cont ze two 500 ga ree stages of scf/bbl N2. inger. NU 1-1 off sub. Cle When coiled t ssembly. est.	OTHER: of give pertinent dates, includ (Morrow) as f watch for 20 m crol HCL acid us llon 50# CMHPG 1000 gallons wi Flow well back /4" coiled tubi	ding estimated date of starting any proposed Follows: minutes. Swab to seating nipp sing 20% mutual solvent. Ener polymer based foam diversion ith ball sealers. Flush with
<ul> <li>12. Describe Proposed or Completed Opwork) SEE RULE 1103.</li> <li>Propose to acidize p</li> <li>1. Pressure tubing</li> <li>2. Acidize with 300 acid w/1750 scf/bbl</li> <li>plugs dividing the a 30 bbls 3% KCL wate</li> <li>3. Flange in coiled ended coiled tubing coiled tubing and sepump off plug and je</li> <li>4. Jet in production</li> <li>5. Place well back</li> </ul>	perforations perforation annulus to 00 gallons N2. Utili acid in thr r with 3000 d tubing ha with pump et slips. et nozzle a on. Flow t into produ	te all periment details, and s 13582-13711 2000 psi and 10% iron cont ze two 500 ga ree stages of scf/bbl N2. anger. NU 1-1 off sub. Cle When coiled t ssembly. est. sction.	OTHER: of give pertinent dates, includ (Morrow) as f watch for 20 m rol HCL acid us llon 50# CMHPG 1000 gallons wi Flow well back /4" coiled tubi ean out to 13800 rubing in instal	ding estimated date of starting any proposed follows: sing 20% mutual solvent. Ener polymer based foam diversion ith ball sealers. Flush with t. ing unit. TIH with jet nozzle o'. Pull up to 13550'. Cut
<ul> <li>12. Describe Proposed or Completed Opwork) SEE RULE 1103.</li> <li>Propose to acidize p</li> <li>1. Pressure tubing</li> <li>2. Acidize with 300 acid w/1750 scf/bbl</li> <li>plugs dividing the a 30 bbls 3% KCL water</li> <li>3. Flange in coiled ended coiled tubing coiled tubing and se pump off plug and jet</li> <li>4. Jet in production</li> <li>5. Place well back</li> </ul>	perforations perforation annulus to 00 gallons N2. Utili acid in thr r with 3000 d tubing ha with pump et slips. et nozzle a on. Flow t into produ	te all periment details, and s 13582-13711 2000 psi and 10% iron cont ze two 500 ga ree stages of scf/bbl N2. anger. NU 1-1 off sub. Cle When coiled t ssembly. est. sction.	OTHER: of give pertinent dates, includ .' (Morrow) as f l watch for 20 m crol HCL acid us 110n 50# CMHPG 1000 gallons wi Flow well back ./4" coiled tubi can out to 13800 cubing in instal	ding estimated date of starting any proposed follows: minutes. Swab to seating nipp sing 20% mutual solvent. Ener polymer based foam diversion ith ball sealers. Flush with the sealers. Contemport ith ball sealers. Contemport the sealers of the sealers of the sealers of the sealers the sealers of the sealers of the sealers the sealers of the sealers of the sealers the sealers of the sealers of the sealers of the sealers the sealers of the sealers of the sealers of the sealers the sealers of the sealers of the sealers of the sealers the sealers of the se
<ul> <li>12. Describe Proposed or Completed Opwork) SEE RULE 1103.</li> <li>Propose to acidize p</li> <li>1. Pressure tubing</li> <li>2. Acidize with 300 acid w/1750 scf/bbl</li> <li>plugs dividing the arrow of the second seco</li></ul>	perforations (Clearly sta perforation annulus to 00 gallons N2. Utili acid in thr r with 3000 d tubing ha with pump et slips. et nozzle a on. Flow t into produ	te all periment details, and as 13582-13711 2000 psi and 10% iron cont ze two 500 ga ree stages of scf/bbl N2. anger. NU 1-1 off sub. Cle When coiled t ssembly. est. action.	OTHER: of give pertinent dates, includ .' (Morrow) as f l watch for 20 m crol HCL acid us 110n 50# CMHPG 1000 gallons wi Flow well back ./4" coiled tubi can out to 13800 cubing in instal	ding estimated date of starting any proposed Follows: minutes. Swab to seating nipp sing 20% mutual solvent. Ener polymer based foam diversion ith ball sealers. Flush with the ing unit. TIH with jet nozzle o'. Pull up to 13550'. Cut led, pressure CT with N2 to
12. Describe Proposed or Completed Op work) SEE RULE 1103. Propose to acidize 1 1. Pressure tubing 2. Acidize with 300 acid w/1750 scf/bbl plugs dividing the a 30 bbls 3% KCL water 3. Flange in coiled ended coiled tubing coiled tubing and so pump off plug and jo 4. Jet in production 5. Place well back Ihereby certify that the information above into skonature Market Rusty Klest	perforations (Clearly sta perforation annulus to 00 gallons N2. Utili acid in thr r with 3000 d tubing ha with pump et slips. et nozzle a on. Flow t into produ	te all periment details, and as 13582-13711 2000 psi and 10% iron cont ze two 500 ga ree stages of scf/bbl N2. anger. NU 1-1 off sub. Cle When coiled t assembly. est. action. <b>best of my knowledge and h</b>	OTHER: of give pertinent dates, includ .' (Morrow) as f l watch for 20 m crol HCL acid us 110n 50# CMHPG 1000 gallons wi Flow well back ./4" coiled tubi can out to 13800 cubing in instal	ding estimated date of starting any proposed Tollows: minutes. Swab to seating nipp sing 20% mutual solvent. Ener polymer based foam diversion th ball sealers. Flush with th ball sealers. Flush with the ing unit. TIH with jet nozzle o'. Pull up to 13550'. Cut led, pressure CT with N2 to echnician DATE Oct. 7, 1998
<ul> <li>12. Describe Proposed or Completed Opwork) SEE RULE 1103. Propose to acidize p <ol> <li>Propose to acidize p</li> <li>Propose to acidize p</li> <li>Acidize with 300 acid w/1750 scf/bbl plugs dividing the a 30 bbls 3% KCL water</li> <li>3. Flange in coiled ended coiled tubing coiled tubing and se pump off plug and jo</li> <li>Jet in production for the place well back</li> </ol> </li> <li>I hereby certify that the information above is a store and a second acid water of the place well back</li> </ul>	verations (Clearly sta perforation annulus to 00 gallons N2. Utili acid in thr r with 3000 d tubing ha with pump et slips. et nozzle a on. Flow t into produ	te all periment details, and as 13582-13711 2000 psi and 10% iron cont ze two 500 ga ree stages of scf/bbl N2. anger. NU 1-1 off sub. Cle When coiled t assembly. est. action. <b>best of my knowledge and h</b> <b>mage</b>	OTHER: ad give pertinent dates, includ .' (Morrow) as f l watch for 20 m rol HCL acid us 11on 50# CMHPG 1000 gallons wi Flow well back ./4" coiled tubi can out to 13800 subing in instal	ding estimated date of starting any proposed Tollows: minutes. Swab to seating nipp sing 20% mutual solvent. Ener polymer based foam diversion th ball sealers. Flush with th ball sealers. Flush with the ing unit. TIH with jet nozzle o'. Pull up to 13550'. Cut led, pressure CT with N2 to echnician DATE Oct. 7, 1998
12. Describe Proposed or Completed Op work) SEE RULE 1103. Propose to acidize p 1. Pressure tubing 2. Acidize with 300 acid w/1750 scf/bbl plugs dividing the a 30 bbls 3% KCL water 3. Flange in coiled ended coiled tubing coiled tubing and so pump off plug and jo 4. Jet in production 5. Place well back I hereby certify that the information above is to skonature Rusty Kle: TYPE OR PRDAT NAME Rusty Kle:	verations (Clearly sta perforation annulus to 00 gallons N2. Utili acid in thr r with 3000 d tubing ha with pump et slips. et nozzle a on. Flow t into produ	te all periment details, and as 13582-13711 2000 psi and 10% iron cont ze two 500 ga ree stages of scf/bbl N2. anger. NU 1-1 off sub. Cle When coiled t assembly. est. action. best of my knowledge and N multiple by z	OTHER: ad give pertinent dates, includ .' (Morrow) as f l watch for 20 m rol HCL acid us 11on 50# CMHPG 1000 gallons wi Flow well back ./4" coiled tubi can out to 13800 subing in instal	ding estimated date of starting any proposed Follows: minutes. Swab to seating nipp sing 20% mutual solvent. Ener polymer based foam diversion ith ball sealers. Flush with the ing unit. TIH with jet nozzle o'. Pull up to 13550'. Cut led, pressure CT with N2 to echnician DATE Oct. 7, 1998 TELEPHONE NO. 505/748-

0	V
ł	j