

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

N.M. Oil Cons. Division

1625 N. French Dr.  
Hobbs, NM 88240

5. Lease Designation and Serial No.  
NMNM96239  
If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Concho Resources Inc.

3. Address and Telephone No.

110 W. Louisiana, Ste 410; Midland, Tx 79701 (915) 683-7443

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UL: H; 1980' FNL & 660' FEL, Sec. 23, T-23S, R-32E

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Diamondtail 23 Federal #2

9. API Well No.

30025-33653

10. Field and Pool, or Exploratory Area

Delaware Brushy Canyon

11. County or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☒ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water


(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

CONCHO RESOURCES INC. RESPECTFULLY REQUESTS APPROVAL TO PLUGBACK THE DIAMONDTAIL '23' FEDERAL NO. 2 WELL ACCORDING TO THE FOLLOWING PROCEDURE:

1. POOH W/ TBG.
2. RIH W/ 5-1/2" CIBP & SET @ 10750'. DUMP 35' OF CMT ON TOP. (ABANDON BONE SPRING PERFS)
3. RIH W/ 4" CSG GUN & PERF @ 7119-25 (13 SHOTS)
4. ACIDIZE ZONE W/ 1000 GALS 7.5% NEFE ACID.
5. RIH W/ TBG, RODS, & PUMP. RETURN WELL TO PRODUCTION.

IF ZONE IS NON-PRODUCTIVE - CONVERT TO SWD IN ZONE @ 5950-6065'. SWD APPROVAL REQUEST TO FOLLOW.



14. I hereby certify that the foregoing is true and correct

Signed

Title PRODUCTION ANALYST

Date 10/26/99

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: