

Submit 3 Copies to Appropriate District
Office

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

FORM C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-33794
1. Type of Well: <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. Indicate Type of Lease <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE
2. Name of Operator Apache Corporation		6. State Oil & Gas Lease No.
3. Address of Operator 2000 Post Oak Blvd., Ste. 100, Houston, Texas 77056-4400		7. Lease Name or Unit Agreement Name A B Baker
4. Well Location Unit Letter <u>I</u> : <u>2135</u> Feet From The <u>South</u> Line and <u>829</u> Feet From The <u>East</u> Line Section <u>10</u> Township <u>22S</u> Range <u>37E</u> NMPM <u>Lea</u> County		8. Well No. 6
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3385' GR		9. Pool name or Wildcat Blinebry Oil & Gas (Pro Gas) / Wantz Abo

11.

NOTICE OF INTENTION TO:

- ☐ Perform Remedial Work ☐ Plug and Abandon
☐ Temporarily Abandon ☐ Change Plans
☐ Pull or Alter Casing
☐ Other

SUBSEQUENT REPORT OF:

- ☐ Remedial Work ☐ Altering Casing
☐ Commence Drilling Operations ☐ Plug and Abandonment
☐ Casing Test and Cement Job
☒ Other Re-Activate Wantz Abo / Downhole
Commingle w/ Blinebry (Pro Gas)

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/1/01 MIRU & pull out of hole w/ production equipment

OPCH 3/2/01 Run in hole w/ bit, tag fill @ 6413'. Cleanout fill & drill out CIBP. Tag bottom @ 7153'.

3/5/01 Pull out of hole w/ bit. Run in hole w/ tubing. Rig up swab. Swab 31 bbls of water in 11 runs. IFL @ 5700', FFL @ 6100'.

3/6/01 Shut in casing pressure - 250#. Rig up swab. SFL @ 6000'. Made 23 runs, FFL @ 6200'. Recovered 52 bbls of water.

3/7/00 Shut in for pressure build up

3/16/01 MIRU. Run in hole w/ 2-7/8" tubing and set @ 7077'. Prep to set pumping unit.

3/19/01 Set pumping unit. Run electricity. Return to production downhole commingled in Blinebry O&G (Pro Gas) and Wantz Abo.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Debra J. Anderson

TITLE

Sr. Engineering Technician

DATE

4/27/01

TYPE OR PRINT NAME

Debra J. Anderson

TELEPHONE NO.

713-296-6338

(This space for State Use)

APPROVED BY

Paul Kautz
Geologist

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: