

1. CDT 2 M 5 0'

<u>Depth</u>	<u>Deviation</u>
0 - 1000	1 degree
1000 - 2000	2 degrees
2000 - 3000	3 degrees
3000 - 4000	4 degrees
4000 - TD	5 degrees

Surveys:

1. Run GR-Sonic Log from base of surface csg to TD w/detailed section as required.
2. Run Laterolog through detailed section.
3. Run temperature survey in production csg after WOC 8 hrs.
4. Run Gamma-Ray log w/collar locator through pay section for perforating control.

Completion:

To be determined at TD.

ORIGINAL SIGNED BY:
APPROVED: C. W. NANCE
C. W. Nance

ORIGINAL
APPROVED: SIGNED BY A. W. LANG
A. W. Lang