

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-6622	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Kern County Land Company		State 36
3. Address of Operator		9. Well No.
418 First State Bank Bldg., Midland, Texas 79701		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>D</u> , <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM		El Mar Delaware
THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>26S</u> RANGE <u>32E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3109' RT		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Kill well down casing with lease crude.
2. Pull tubing and lay down packer and hold down. Knock out bridge plug at 4606' exposing perfs 4609-4619'.
3. Frac down 4 1/2" casing with 1000 gal refined oil pad followed by 3000 gal refined oil and 4500# 10-20 m. sand.
4. Run tubing, pump and rods.
5. Install pumping unit. Place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>C. F. Euston</u>	TITLE <u>District Engineer</u>	DATE <u>9-14-65</u>
APPROVED BY <u></u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		