

Lewis B. Burleson
Stevens A-34 No. 2

12/28/94 Move in, pull tubing, run bit and scraper to 3000', pull out, run cast iron bridge plug 5½ to 3000', set, spot 15 sacks cement on top, pull tubing out, shut down.

12/29/94 Tag cement at 2825', pull to 1400', spot 25 sacks, pull out, wait on cement, tag at 1148', pull tubing to 100', circulate cement to surface.

12/30/94 Cut off wellhead, put in marker, rig down, move to new location.

Class "C" Cement
Mud 25lb. Salt Gel per bbl.

505-392-6591 • P.O. BOX 2545 • HOBBS, NEW MEXICO 88241

HOBBS, NEW MEXICO	(505)	392-6591
LAKEVIEW, TEXAS	(915)	523-4420

EUNICE, NEW MEXICO (505) 394-2557
MIDLAND, TEXAS (915) 685-8555