

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Skelly Penrose "A" Unit
2. Name of Operator Skelly Oil Company	8. Farm or Lease Name Skelly Penrose "A" Unit
3. Address of Operator P. O. Box 1351, Midland, Texas 79701	9. Well No. 62
4. Location of Well UNIT LETTER K , 2200 FEET FROM THE South LINE AND 2200 FEET FROM THE West LINE, SECTION 3 TOWNSHIP 23S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Langlie-Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3307' DF	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Perforate, test & equip to pump <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was formerly Skelly Oil Company's R. R. Sims Well No. 7, producing from the Blinebry zone. The Blinebry zone has been plugged and abandoned. We propose to complete this well as Skelly's Penrose "A" Well No. 62 by performing the following work:

- 1) Move in pulling unit.
- 2) Spot 500 gallons of 7-1/2% acid.
- 3) Run Gamma Ray-Neutron Log from 3720' to 2700'.
- 4) Perforate 9-5/8" casing in the Penrose zone with 2 shots per foot as indicated by Gamma Ray-Neutron Log.
- 5) Treat perforated interval with 1500 gallons of 15% acid.
- 6) Run tubing, rods, and pump. Install pumping equipment.
- 7) Connect to flow line.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. R. Crow TITLE Lead Clerk DATE March 19, 1973

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: