11 1	of New Mexico	Form C-1
District I	ils and Natural Resources	Revised March 25, 1 WELL API NO.
1625 N. French Dr., Hobbs, NM 87240		
811 South First, Artesia, NW 8/210	ERVATION DIVISION	30-025-10622
District III 204	0 South Pacheco	5. Indicate Type of Lease
District IV	ta Fe, NM 87505	STATE FEE <b>x</b> 6. State Oil & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505		685270
SUNDRY NOTICES AND REPOR (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT PROPOSALS.)  1. Type of Well:	TO DEEPEN OR PLUG BACK TO A " (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name:  Skelly Penrose 'A' Unit
Oil Well Gas Well Other Inject  2. Name of Operator	ction Well	8. Well No.
Prize Operating Company		34
3. Address of Operator		9. Pool name or Wildcat
3500 William D. Tate, Suite 200, Grapevine 4. Well Location	, Texas 76051	Langlie Mattix 7-Rv Queen
Unit Letter N : 660 feet from	n the <b>South</b> line and	1980 feet from the West li
Section 4 Township	p 23S Range 37E how whether DR, RKB, RT, GR, e	NMPM County Lea
Social To. Elevation (5)	3300' GR	ac.j
EMPOPARII V ARANDONI - CHANCE DI ANG	NDON REMEDIAL WORK	ALTERING CASING
	_	LING OPNS.  PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE COMPLETION	COMMENCE DRIL	LING OPNS. PLUG AND ABANDONMENT D
PULL OR ALTER CASING  MULTIPLE	COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Tempora rly state all pertinent details, and a For Multiple Completions: Attack	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hother tested casing to 505 psi and held for 30	COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Temporal rly state all pertinent details, and get of the completions: Attack	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Ho	COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Temporal rly state all pertinent details, and get of the completions: Attack	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hother tested casing to 505 psi and held for 30	COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Temporal rly state all pertinent details, and get of the completions: Attack	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hothersted casing to 505 psi and held for 30	COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Temporal rly state all pertinent details, and get of the completions: Attack	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hotel Tested casing to 505 psi and held for 30 Left well TA'd	COMMENCE DRILL  CASING TEST AND CEMENT JOB  OTHER: Temporal rly state all pertinent details, and grow Multiple Completions: Attached by the completions of the completion of t	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hotel Tested casing to 505 psi and held for 30 Left well TA'd	COMMENCE DRILL  CASING TEST AND CEMENT JOB  OTHER: Tempora  rly state all pertinent details, and g  For Multiple Completions: Attack  obbs, did not pull tubing/ o minutes.	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hore Tested casing to 505 psi and held for 30 Left well TA'd	COMMENCE DRILL  CASING TEST AND CEMENT JOB  OTHER: Temporal rly state all pertinent details, and grow Multiple Completions: Attached by the completions of the completion of t	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hotel Tested casing to 505 psi and held for 30 Left well TA'd	COMMENCE DRILL  CASING TEST AND CEMENT JOB  OTHER: Tempora  rly state all pertinent details, and g  For Multiple Completions: Attack  obbs, did not pull tubing/ o minutes.	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hote Tested casing to 505 psi and held for 30 Left well TA'd  The Ab	COMMENCE DRILL CASING TEST AND CEMENT JOB  OTHER: Tempora rly state all pertinent details, and g For Multiple Completions: Attach obbs, did not pull tubing/ o minutes.  Alis Approva of Tempora randonment Expires	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hote Tested casing to 505 psi and held for 30 Left well TA'd  The Above certify that the information above is true and complete to the compl	CASING TEST AND CEMENT JOB  OTHER: Temporal of Tempora	PLUG AND ABANDONMENT  D  Try Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hote Tested casing to 505 psi and held for 30 Left well TA'd  The Above certify that the information above is true and complete to the compl	COMMENCE DRILL CASING TEST AND CEMENT JOB  OTHER: Tempora rly state all pertinent details, and g For Multiple Completions: Attach obbs, did not pull tubing/ o minutes.  Alis Approva of Tempora randonment Expires	PLUG AND ABANDONMENT  D  Try Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hote Tested casing to 505 psi and held for 30 Left well TA'd  The Above Certify that the information above is true and complete to GNATURE As A DAMAGE COMPLETION	CASING TEST AND CEMENT JOB  OTHER: Temporal of Tempora	PLUG AND ABANDONMENT  Pry Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.  Page 15   10   10   10   10   10   10   10
PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Hotel Tested casing to 505 psi and held for 30 Left well TA'd	CASING TEST AND CEMENT JOB  OTHER: Temporal of Tempora	PLUG AND ABANDONMENT  D  TY Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  DATE 3-6-2002
DTHER:  12. Describe Proposed or Completed Operations (Clear of starting any proposed work). SEE RULE 1103. If or recompilation.  Per conversation with Sylvia w/OCD in Horested casing to 505 psi and held for 30 Left well TA'd  The Above certify that the information above is true and complete to GNATURE  OPERATURE  OPERATURE  DOI Aldridge	CASING TEST AND CEMENT JOB  OTHER: Temporal of Tempora	PLUG AND ABANDONMENT  Pry Abandonment  give pertinent dates, including estimated date h wellbore diagram of proposed completion  packer.  Page 15   10   10   10   10   10   10   10

