Submit 3 Copies To Appropriate District State of New Office E1gy, Minerals and N			ces	Form C-103 Revised March 25, 1999				
1625 N. French Dr., Hobbs, NM 87240 District II 811 South First, Artesia, NM 87210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 2040 South Pacheco, Santa Fe, NM 87505	OIL CONSERVATION DIVISION 2040 South Pacheco Santa Fe, NM 87505			WELL API NO.         30-025-10623         5. Indicate Type of Lease         STATE       FEE         6. State Oil & Gas Lease No.				
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well Gas Well	ATION FOR PERMIT" (FORM	EPEN OR PLUG BA M C-101) FOR SUCH	CK TO A		Name or U	nit Agreement Nan A' Unit	ne:	
1. Type of Well: Oil Well Gas Well Other TA'd Oil well         2. Name of Operator         Prize Operating Company         3. Address of Operator         3500 William D. Tate, Suite 200, Grapevine, Texas 76051         4. Well Location			8	B. Well N	0.			
Prize Operating Company				33				
<ol> <li>Address of Operator</li> <li>3500 William D. Tate, Suite 200, Grapevine, Texas 76051</li> <li>Well Location</li> </ol>				9. Pool name or Wildcat Langlie Mattix 7 RVRS Queen GRBY				
Unit Letter <u>M</u> :	500 feet from the	South lin	e and	990	feet from	the West	line	
Section 4	Township 23	s Range	37 E	NMPM		County Le	a	
	10. Elevation (Show wh							
11. Check A	ppropriate Box to Ind	icate <sub>l</sub> Nature of	Notice, Re	eport, or	Other D	ata		
NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:					
	PLUG AND ABANDON		WORK			ALTERING CASIN	ig 🗌	
	CHANGE PLANS			G OPNS.		PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION							
OTHER: Return TA'd well to pr	oduction							

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Well is currently TA'd. Prize requests approval to RIH with bit and drill out CIBP and clean out to +/- 3560' (pressure test hole prior to drilling out CIBP). RIH with packer and set @ +/- 3500' and test casing for any leaks. If any, squeeze and swab perfs 3526-3636 for clean up. Place on production.

I hereby certify that the information above is true and complete to the SIGNATURE	ne best of my knowledge and belief.		DATE <b>8-2-2001</b>	
Type or print name Don Aldridge			Telephone No.	817-424-0454
(This space for State use)		in Clarad he	. <u>.</u> .	
APPROVED BY Conditions of approval, if any:	TITLĘ	.40 hornin	DATE	<b>;</b>

## SKELLY PENROSE FIELD # 33 Reactivate Well

## Procedure:

- 1. MIRU Workover Rig. POH with tubing.
- Pick up 2 3/8" workstring and RIH with bit and drill out CIBP at +/-3476'. Clean out to +/-3650'. Pressure test hole prior to drilling out CIBP.
- 3. RIH with packer and set at +/-3500' and pressure test casing. Isolate and squeeze any casing leaks. Otherwise, swab perfs 3526'-3636' for clean-up. Report rate and cut. POH. RIH with rental PC pump from From Paradigm if swabbing at a high rate. RDMO. Place well on production.

Note: Contact at Paradign is Bob Callier 915-683-6696





