STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

48. 87 COPIES ACCEIVES	T	
DISTRIBUTION	1	
SANTA FE		
FILE		
U.S.G.S.		_
LAND OFFICE	1	
OPERATOR		

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Fo	rn	C - 1	03	
Re	v i s	e đ	10-1	-

U.S.G.S.	1 013 22000 7 0		<u> </u>
	O+2 - NMOCD-P.O. Box 19	980 l - Foreman	5a. Indicata Type of Lease
LAND OFFICE	Hobbs, NM 88240	1 - WIO's	State Too X
OPERATOR	1 - Engr.		5. State Oil & Gas Lease No.
	- ingt.	l - File	of order off d dds Ledse No.
SUNDF	RY NOTICES AND REPORTS ON WELLS		mmmmmmm
(DO NOT USE THIS FORM FOR PR. USE "APPLICAT	OPOSALS TO DHILL OF TO DEEPEN OR PLUG BACK TO A FION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOS	OIFFERENT RESERVOIR,	
J** —			7. Unit Agreement Name
WELL WELL	OTHER- Injection Wells		The state of the s
2. Name of Operator			8. Farm or Lease Name
Getty Oil Company	•		1 .
3. Address of Operator			Skelly Penrose Band
P. O. Box 730 Hobbs,	NM 88240		
4. Location of Well	NH 00240		19
В	660 North	1000	10. Field and Pool, or Wildcat
UNIT LETTER	660 FEET FROM THE North	1980 FEET FROM	Langlie Mattix
East	. 5	0.55	
THE LINE, SECTI	. 5 23S	37E	
mmmmmi		· 	
	15. Elevation (Show whether DF, RT,	GR, etc.)	12. County
<i>İHHHHHHHH</i>	3365' DF		Lea
Check	Appropriate Box To Indicate Nature o	ENotice Roport or Or	has David
. NOTICE OF I	NTENTION TO:	superior of of	ner Data
•		SOUSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIA	LL WORK	
TEMPORARILY ABANDON			ALTERING CASING
;= -{	COMMEN	CE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING	CE DRILLING OPNS.	<u> </u>
PULL OR ALTER CASING	COMMEN	CE DRILLING OPNS.	<u> </u>
PULL OR ALTER CASING	CHANGE PLANS CASING OTHE	CE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING OTHE	CE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING	CE DRILLING OPNS.	PLUG AND ABANDONMENT
OTHER OTHER 17. Describe Proposed or Completed Opmork) SEE RULE 1103.	CHANGE PLANS CASING OTHE	CE DRILLING OPNS.	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Or work) SEE RULE 1103.	CHANGE PLANS COMMEN CASING OTHE Perations (Clearly state all pertinent details, and a flow well back vigorously.	CE DRILLING OPNS. TEST AND CEMENT JQB R Tive pertinent dates, including	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Or work) SEE RULE 1103. 1. Shut injection and 2. Rig up pulling uni	perations (Clearly state all pertinent details, and all flow well back vigorously. it, install BOP, and pull tubing	TEST AND CEMENT JQB	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Or work) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin	CHANGE PLANS COMMEN CASING OTHE Perations (Clearly state all pertinent details, and a flow well back vigorously.	TEST AND CEMENT JQB	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Opwork) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH.	perations (Clearly state all pertinent details, and and fill the state of the state	TEST AND CEMENT JQB R give pertinent dates, including	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Or work) see Rule 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin	perations (Clearly state all pertinent details, and and follows well back vigorously. it, install BOP, and pull tubing, collars, and bit and clean in a gand packer. Set packer 80 for	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Or work) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin 6. Acidize with 1500	perations (Clearly state all pertinent details, and all flow well back vigorously. it, install BOP, and pull tubing, collars, and bit and clean and gand packer. Set packer 80 ft to 2000 gals. of 60/40 mixture	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Or work) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin 6. Acidize with 1500	perations (Clearly state all pertinent details, and all flow well back vigorously. it, install BOP, and pull tubing, collars, and bit and clean and gand packer. Set packer 80 ft to 2000 gals. of 60/40 mixture	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Or work) SEE RULE 1103. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin 6. Acidize with 1500 7. Shut in for four h	perations (Clearly state all pertinent details, and and follow well back vigorously. it, install BOP, and pull tubing, collars, and bit and clean and gand packer. Set packer 80 for to 2000 gals. of 60/40 mixture hours:	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Opwork) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin 6. Acidize with 1500 7. Shut in for four h 8. Flow back vigorous	Perations (Clearly state all pertinent details, and and follow well back vigorously. It, install BOP, and pull tubing, collars, and bit and clean in the state of the state o	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT
17. Describe Proposed or Completed On work) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin 6. Acidize with 1500 7. Shut in for four h 8. Flow back vigorous 9. Run injection tubi	perations (Clearly state all pertinent details, and and follow well back vigorously. It, install BOP, and pull tubing, collars, and bit and clean the gand packer. Set packer 80 ft to 2000 gals. of 60/40 mixture nours:	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Opwork) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin 6. Acidize with 1500 7. Shut in for four h 8. Flow back vigorous	perations (Clearly state all pertinent details, and and follow well back vigorously. It, install BOP, and pull tubing, collars, and bit and clean the gand packer. Set packer 80 ft to 2000 gals. of 60/40 mixture nours:	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT
17. Describe Proposed or Completed On work) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin 6. Acidize with 1500 7. Shut in for four h 8. Flow back vigorous 9. Run injection tubi	perations (Clearly state all pertinent details, and and follow well back vigorously. It, install BOP, and pull tubing, collars, and bit and clean the gand packer. Set packer 80 ft to 2000 gals. of 60/40 mixture nours:	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT
17. Describe Proposed or Completed On work) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin 6. Acidize with 1500 7. Shut in for four h 8. Flow back vigorous 9. Run injection tubi	perations (Clearly state all pertinent details, and and follow well back vigorously. It, install BOP, and pull tubing, collars, and bit and clean the gand packer. Set packer 80 ft to 2000 gals. of 60/40 mixture nours:	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT
17. Describe Proposed or Completed On work) SEE RULE 1703. 1. Shut injection and 2. Rig up pulling uni 3. GIH with workstrin 4. POH. 5. GIH with workstrin 6. Acidize with 1500 7. Shut in for four h 8. Flow back vigorous 9. Run injection tubi	perations (Clearly state all pertinent details, and and follow well back vigorously. It, install BOP, and pull tubing, collars, and bit and clean the gand packer. Set packer 80 ft to 2000 gals. of 60/40 mixture nours:	TEST AND CEMENT JQB TO	PLUG AND ABANDONMENT

18. I hereby certs	fy that the information above is true a	nd complete to the best of my knowledge and belief.	
16×60	le programme fut	Area Superintendent	DATE 9/17/81
	Jerry Sexton Dist 1, Supv.		007 3 1981
PROVED BY	Dist 1, Supe	TITLE	PATE