

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection		7. Unit Agreement Name Skelly Penrose "B" Unit
2. Name of Operator Skelly Oil Company		8. Farm or Lease Name Skelly Penrose "B" Unit
3. Address of Operator P. O. Box 1351, Midland, Texas 79701		9. Well No. 19
4. Location of Well UNIT LETTER B , 660 FEET FROM THE North LINE AND 1980 FEET FROM East LINE, SECTION 5 TOWNSHIP 23S RANGE 37E NMPM. Langlie-Mattix		10. Field and Pool, or Wildcat Langlie-Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3365' D. F.		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Squeeze existing perfs. and reperforate <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Rig up workover rig. Pull tubing and packer.
- 2) Clean out with bit to 3733'.
- 3) Squeeze off existing perfs. 3648-3733'.
- 4) Drill out to 3720'.
- 5) Spot 250 gals. 7-1/2% acid and perforate with one shot per interval at: 3645', 3659', 3664', 3676', 3683', 3698', and 3707'.
- 6) Set RTTS Tool at approximately 3600' and acidize perfs. with 750 gallons 15% NE acid and ball sealers.
- 7) Load casing annulus with water treated with inhibitors.
- 8) Rerun injection tubing, set packer and resume injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____

TITLE **Lead Clerk**

DATE **June 15, 1972**

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

Orig. Signed by
Joe D. Runney
Dist. I, Supv.

TITLE _____

DATE _____

JUN 19 1972

RECEIVED

JUN 10 1972

OIL CONSERVATION COMM.
HOBBS, N. M.