		Form C-193
DISTRIBUTION		Supersedes Old C+102 and C+103
SANTA FE	NEW MEXICO OIL CONSERVATION ENLISE OF VE	Effective 1-1-65
FILE		
U.S.G.S.	MAR 2 o 1970	5a. Indicate Type of Lease
LAND OFFICE	- 1310 C & MAIN	State in ee
DPERATOR	OIL CONSERVATION CO	5, State Oil & Gas Lease No.
	HODDO H	MM.
SUNDI	RY NOTICES AND REPORTS ON WELLS HOBBS, N. M.	
USE "APPLICA	TION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS,	7. Unit Agreement Name
OIL GAS		i Chic ngieem ii watte
well well well.	OTHER.	Furmicritedse Jame
Sun	Oil Company	A. D. Richards
3. Address of Operator		9. 4-11 Me.
P. 0	). Box 2792, Odessa, Texas 79760	5
. Location of Well		10. Field and Fool, or Wikipat
UNIT LETTER D	430 FEET FROM THE West LINE AND 660 FEET FROM	Langlie-Mattix
THE North LINE, SECT	10N	
mmmm	15. Elevation (Show wheth " DF, RT, GR, etc.)	2. County
	3390 Gr.	Lea
Chlo		
	Appropriate Box To Indicate Nature of Notice, Report or Ot INTENTION TO: SUBSEQUEN	ner Data T REPORT OF:
NOTICE OF	30B3EQUEN	TREFORT OF.
PERFORM REMEDIAL WORK	PLUG AND ABANDON TO REMEDIAL WORK	ACTERNO CASINO
·	1—————————————————————————————————————	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PEUG AND ABANDONMENT
-	CHANGE PLANS CASING YEST AND CEMENT JOB	PUDG AND RANDUMMENT (
		PARMADOZABA DVA DUDS
-	CHANGE PLANS CASING YEST AND CEMENT JOB	r -
17. Describe Proposed or Completed ( work) SEE RULE 1109.	CHANGE PLANS CASING YEST AND CEMENT JOB	estimated date of starting any process
other P&S standing we.  17. Describe Proposed or Completed Cowork, SEE RULE 1109.  Move in wire line union CIBP. Load hole to	CHANGE PLANS CASING YEST AND CEMENT JOB  OTHER  Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting and produce
other P& standing we.  7. Describe Proposed or Completed Company SEE RULE 1103.  Move in wire line union CIBP. Lead hole weld plate on casing.	change Plans Casing Yest and Cement Job Other  Department (Clearly state all pertinent details, and give pertinent dates, including it with mast; run and set cast iron bridge plug (W/mmd(gel brine), salvage x-mas tree. Place 10)	estimated date of starting and produce in 3600°, dump 2 sks cemes sk cement plug @ surface
other P& standing we.  7. Describe Proposed of Completed (work) SEE RULE 1103.  Move in wire line union CIBP. Load hole weld plate on casing	Operations (Clearly state all pertinent datails, and give pertinent datas, including it with mast; run and set cast iron bridge plug (a/mud(gel brine), salvage x-mas tree. Place 10 install permanent well marker.	estimated date of starting and produce in 3600°, dump 2 sks cemes sk cement plug @ surface
other P& standing we.  7. Describe Proposed or Completed Complete Completed Complete	Operations (Clearly state all pertinent datails, and give pertinent datas, including it with mast; run and set cast iron bridge plug (a/mud(gel brine), salvage x-mas tree. Place 10 install permanent well marker.	estimated date of starting and produce of 3600°, dump 2 sks cemes sk cement plug @ surface