

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection	7. Unit Agreement Name Skelly Penrose "A" Unit
2. Name of Operator Skelly Oil Company	8. Farm or Lease Name Skelly Penrose "A" Unit
3. Address of Operator P. O. Box 1351, Midland, Texas 79701	9. Well No. 42
4. Location of Well UNIT LETTER B , 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 23S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Langlie-Mattix
11. Elevation (Show whether DF, RT, GR, etc.) 3296' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Install, cement & perforate liner <input checked="" type="checkbox"/>	CASING TEST AND CEMENT LOG <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To improve vertical distribution in Penrose Sand interval and sweep efficiency, we propose the following:

- 1) Rig up workover rig. Pull tubing and packer.
- 2) Knock Caliper -- lost in May, 1972 -- to bottom to set liner at least to 3619'.
- 3) Run 5" OD liner inside 7" OD casing. Set liner hanger at approximately 3300' and bottom of liner at TD.
- 4) Cement liner and allow to set 24 hours.
- 5) Run Temperature Survey; and if cement did not circulate, squeeze top of liner and let cement set up for 24 hours.
- 6) Clean out inside liner to approximately 3619'.
- 7) Spot 500 gals. 7-1/2% acid and run Gamma Ray Neutron Collar Log from PBTD to 2600'.
- 8) Perforate 5" OD liner in Penrose zone with one shot per foot as indicated by GRN log.
- 9) Treat perforated interval with 750 gals. 15% acid and ball sealers.
- 10) Run 2-3/8" OD cement-lined tubing, load casing annulus behind tubing with water treated with inhibitors and set packer at approximately 3351'.
- 11) Hook well to injection system, resume injection and, after two weeks' stabilized injection, run injection profile.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(Signed) **D. R. Crow**

Lead Clerk

Sept. 25, 1972

SIGNED _____ TITLE _____ DATE _____

Orig. Signed by

Joe D. Ramsey

Dist. I. Supv.

APPROVED BY _____ TITLE _____ DATE **SEP 27 1972**

CONDITIONS OF APPROVAL, IF ANY: